

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R14245. LEASE DESIGNATION AND SERIAL NO.
SF-080362

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Waterflow

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat11. SEC. T., R., M., OR B.L.K. AND
SURVEY OR AREA**9, T-30-N, R-15-W**

12. COUNTY OR PARISH

San Juan

13. STATE

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole	
2. NAME OF OPERATOR Davis Oil Company	
3. ADDRESS OF OPERATOR 1020 Midland Savings Building	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' from South and West lines Section 9, T-30-N, R-15-W San Juan County, New Mexico	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5316' Gr 5327' K B

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Reached total depth at 4363' on October 29, 1963. Ran Schlumberger Induction Electrical Log and Sonic Log - Gamma to T.D. Propose to set following cement plugs prior to abandonment.

5 sacks at surface with dry hole marker
10 sacks at base of surface pipe (132')
20 sacks from 1050' to 1150'
30 sacks from 2850' to 3000
40 sacks from 4150' to 4360'



18. I hereby certify that the foregoing is true and correct

SIGNED

Harrell Budd
Harrell BuddTITLE **Consulting Geologist**DATE **12/9/63**

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: