

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Jensen	
9. Well No. 1	
10. Field and Pool, or Wildcat Aztec, PC	
12. County San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-

2. Name of Operator
C. & E. Operators, Inc.

3. Address of Operator
Suite 1100, Two Energy Square
4849 Greenville Ave., Dallas, Texas 75206

4. Location of Well
UNIT LETTER I 1827 FEET FROM THE South LINE AND 790 FEET FROM
THE East LINE, SECTION 12 TOWNSHIP 30 North RANGE 12 West N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
5886' Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

November 12 through November 17, 1986 Plug and Abandon well by Bedford, Inc., Farmington, New Mexico.

(See Attached Bedford Progress Report for job details)

Plug #1 2118' back to 1883' w/50 sx.
#2 1237' back to 1000' w/100 sx.
#3 577' back to 477' w/50 sx.
#4 122' back to surface w/20 sx.
Pump 15 sx. down bradenhead.

Dry hole marker installed, pits filled and surface equipment removed and location cleaned up by Townsend Roustabout, Aztec, N. M. Checked 12/2/86.

RECEIVED

DEC 04 1986

CON. DIV.
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John M. Keller
John M. Keller

TITLE Field Agent
P. O. Box 1507, Durango, Colo.

DATE Dec. 3, 1986

Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE DEC 09 1986

CONDITIONS OF APPROVAL, IF ANY:



BEDFORD INC.

P. O. BOX E
FARMINGTON, NEW MEXICO
87499

November 17, 1986

C. & E. Operators, Inc.
C/O John M. Heller
P.O. Box 1507
Durango, Colorado 81303

Invoice # 1060

For plug and abandonment of your Jensen # 1
located SE/4, Sec.12, T30N, R12W, San Juan County, New Mexico.

- 11/12/86 Move in. Rig up. Open well to blow down. Shut down.
- 11/13/86 Pick up on tubing. Tubing stuck. Pump 70 bbls water down tubing. No returns. Tubing free. Pull out of hole with 98 joints 1" line pipe. Bottom 18 joints full of holes. Nipple down well head. Nipple up tubing head for 2" tubing. Wait on tubing. Shut down.
- 11/14/86 Went in hole with 65 joints 2" tubing. Spot 50sx plug from 2118' to 1993'. Pull up to 1130'. WOC. Rig up shooter. Tag cement puug at 1883'. Perforated 2 holes at 1237'. Lowered tubing 3 joints. Pump into perfs. to establish rate. Shut down.
- 11/15/86 Spot 100sx at 1237'. Pull out of hole with tubing. Fill hole and squeezed cement thru perfs at 750psi. Left top of cement at 1000'. WOC. Rig up shooter. Perf 2 holes at 577'. Pump 50sx from 577' to 477' in and outside casing and 20sx inside casing from 122' to 0'. Pump 15sx down braden head. Shut down.
- 11/17/86 Check well. All plugs OK. Rig down. Move to yard. As per our letter dated October 24, 1986.

