

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME O. J. Hoover "B"	
2. NAME OF OPERATOR Clinton Oil Company		8. FARM OR LEASE NAME N. E. Hogback Unit	
3. ADDRESS OF OPERATOR 217 North Water, Wichita, Kansas 67202		9. WELL NO. 33	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2120' FSL & 1830' FWL Sec. 11-30N-16W		10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup	
14. PERMIT NO.		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 11-30N-16W	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5440' DF		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU - Pull rods, pump and tubing. Sand pump well to clean out below Gallup perf 1832'-68' & 1938'-61'. Acidize Gallup intervals w/1000 gals 15% Reg HCL using ball sealer. Re-run tubing, pump and rods and put well back on production.



18. I hereby certify that the foregoing is true and correct

SIGNED DA McLean TITLE Dist. Production Engineer DATE 4-27-73

(This space for Federal or State office use)

APPROVED BY 7u TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side