Form 9–331		HAUTED STATE			1	Form approve	d.	
(May 1963)	UNITED STATES SUBMIT IN TRIPLICATED (Other instructions on re-				re-	Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.		
GEOLOGICAL SURVEY •						SF - 078316		
				WELLC			OR TRIBE NAME	
(Do not use this	ORY NO form for prop Use "APPLI	TICES AND REPO	OKIS ON n or plug back to for such proposi	WELLS to a different reservoir. als.)				
OIL GAS WELL WELL	OTHER				7. UNI	T AGREEMENT NA	МВ	
2. NAME OF OPERATOR						8. FARM OR LEASE NAME		
Tenneco Oil Company						Florance		
3. ADDRESS OF OPERATOR								
P. O. Box 1714. Durango, Colorado 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						#16	R WILDCAT	
See also space 17 below.)						anco Mesav	verde and	
1010' FNL 990 FEL						sin Dakota c., t., e., w., or b survey or area	LK. AND	
1010. LMF 330 LEF								
		15, ELEVATIONS (Show	whether DE DT	ate)		. 6, T30N		
14. PERMIT NO.		6374 D			G o	n Juan	New Mexi	
				(N) D - 1		<u> </u>	, HOR PROPER	
16.	Check A	Appropriate Box to In	idicate Natul	e of Notice, Report, c				
	NOTICE OF INT	ENTION TO:		SUB	BEQUENT REP	ORT OF:		
TEST WATER SHUT-0	FF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING V		
FRACTURE TREAT		MULTIPLE COMPLETE	_	FRACTURE TREATMENT		ALTERING CA	 	
SHOOT OR ACIDIZE		ABANDON®	<u></u>	(Other) Deepe	en to Da		x	
REPAIR WELL (Other)	لـــا	CHANGE PLANS		(Note: Report res Completion or Rec	ults of mult	ple completion port and Log for	on Well	
17. DESCRIBE PROPOSED O proposed work. I: nent to this work.)	R COMPLETED O	PERATIONS (Clearly state a tionally drilled, give subst	all pertinent det urface locations	ails, and give pertinent de and measured and true ve	tes, includin	g estimated dat for all markers	e of starting and and zones perti	
Rig up, pu 7" with 49 7751'. Recement. I log, cement per foot. cleaned on 2 holes per Reset BP are 7445' acid	all tubing 50 sacks an 241 jt 100. Dried top at Squeeze at to 772 ar foot. But 7595 Filized with sand f	cement. WOC. s. 4-1/2" 10.5# 1 3d stage coll. 4760'. Tested d with 100 sack 1'. Tested cas Ran BP 7655' a KR at 7535', ac h 340 gal. Fra collowed with 13	Drilled cand 11.6 ar at 429 casing to sement. Ing to 40 and packer idized with 2300 lbs.	Ran cement retainement with 30 km # casing set at 3' and cleaned co 4000# held oke WOC. Drilled 00# okay. Perforat 7595', acidith 340 gal. Res 72-7690 with 79 CO2, set BP at ter and 85,000	7750', out to 7 ay. Per cement Dakota ized wit set BP a 300 gal 5550, p	with 325 721'. Ranf 4730' wiretainer 7472-7690 h 340 galt 7505 PK. water amer Looko	sacks n bond ith 4 hole and with . acid. R at	