

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> 2. Name of Operator U & E Operators, Inc. 3. Address of Operator Two Energy Square-Suite 1100-4849 Greenville Ave.-Dallas, Texas 75206 4. Location of Well UNIT LETTER <u>U</u> <u>690</u> FEET FROM THE <u>South</u> LINE AND <u>1790</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>30N</u> RANGE <u>11W</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 5729	7. Unit Agreement Name 8. Farm or Lease Name Hampton 9. Well No. 2 10. Field and Pool, or Wildcat Aztec PC 12. County San Juan
---	--


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled 89 joints of 1" Tubing  
Perforated from 110' to 112' - 2 shots per ft. 4 shots in area.  
Perforated from 952½ to 954½ - 2 shots per ft. 4 shots in area.  
Plug #1 from 1900 up to 1530  
Plug #2 from 925.5 up to 686  
Plug #3 from 110 to surface w/ 175 total lbs of cement  
Set dry hole marker - cleaned up location.

P+G 10-15-81



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. R. Cunningham Int. TITLE Agent DATE 10/23/81

APPROVED BY Original Signatures TITLE DEPT. OF ENERGY INSPECTOR DIST #3 DATE NOV 2 1981

CONDITIONS OF APPROVAL, IF ANY: