

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fed. Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Atlantic B
3. Address of Operator Box 990, Farmington, New Mexico	9. Well No. #8 (OWWO)
4. Location of Well UNIT LETTER 990 M 990 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 30N RANGE 10W NMPM.	10. Field and Pool, or Wildcat Blanco Mesa Verde
15. Elevation (Show whether DF, RT, GR, etc.) 6367' GL	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Cased & Frac Mesa Verde	CASING TEST AND CEMENT JOB <input type="checkbox"/>	


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to increase production and improve the mechanical condition of this well, it is intended to work it over as follows:

Pull the tubing or cut tubing off and clean out the open hole or drill a new side-tracked hole through the Mesa Verde pay.

Test the 7" casing and repair leaks by squeezing with cement or perforate at the base of the Ojo Alamo and block squeeze cement behind the 7" casing.

Set and cement 4 1/2" production casing, selectively perforate and sand-water fracture the Mesa Verde.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. H. Wood TITLE Petroleum Engineer DATE 11-22-65

APPROVED BY [Signature] TITLE Sup Dist III DATE 11-23-65
CONDITIONS OF APPROVAL, IF ANY: