| Ferm | 9-331 |
|------|-------|
| (May | 1963) |

14. PERMIT NO.

DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

12. COUNTY OR PARISH 13. STATE

New Mexico

San Juan

| GEOLOGICAL SURVEY | S. G. 079439 | |
|---|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME USA | |
| OIL GAS WELL OTHER | 7. UNIT AGREEMENT NAME Horseshoe Gallup Unit | |
| 2. NAME OF OPERATOR Atlantic Richfield Company | 8. FARM OR LEASE NAME Horseshoe Gallup | |
| 1860 Lincoln Street, Suite 501, Denver, Colorado 80203 | 9. WELL NO. 252 | |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface | 10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA | |
| Unit M, 330' f/South & 4510' f/East lines, Section 4 | Sec. 4-30N-16W | |

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

5303' KB

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

| NOTICE OF INTENTION TO: | | | SUBSEQUENT REPORT OF: | | | |
|---|--|--|-----------------------|--|--|--|
| TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) | | PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS | | WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Shut In. (NOTE: Report result Completion or Recompletion or | REPAIRING WELL ALTERING CASING ABANDONMENT* Extension Request lits of multiple completion on W appletion Report and Log form.) | |
| | | | | | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was producing 100% water and was not economical to operate. Ιt was shut in 3-1-68.

This well is in a large Unit which is now under waterflood operations. Future plans are to conduct waterflood and tertiary recovery studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

JUN. 14 1976
NL CON. COM.

Two copies sent to New Mexico Oil Conservation Commission

| 18. | I hereby certify that the foregoing is true and correct | | | | |
|-----|---|---------|--------------------|-------------|--|
| | SIGNED W. A. Waltner, Jr. | TITLE _ | Operations Manager | DATE 6/4/76 | |
| | (This space for Federal or State office use) | <u></u> | | | |
| | APPROVED BY | TITLE _ | | DATE | |