5. LEASE

S.F. 081226

UNITED STATES					
DEPARTMENT	OF	THE	INTERIOR		
GEOLOG	CAL	SUF	VEY		

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Horseshoe Gallup Unit 8. FARM OR LEASE NAME		
1. oil gas Thiochion	Horseshoe Gallup Unit		
well well other Injection 2. NAME OF OPERATOR ARCO Oil and Gas Co., a	9. WELL NO.		
•	259 10. FIELD OR WILDCAT NAME		
Div. of Atlantic Richfield Company 3. ADDRESS OF OPERATOR 707 - 17th Street,	Horseshoe Gallup		
P.O. Box 5540, Denver, Colo. 80217	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA		
below.)	Sec. 3-30N-16W		
AT SURFACE: Unit P,695'FSL & 835'FEL, Sec. 3	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico		
	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5556' GR		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	construence, secretaristic communication de definition of		
FRACTURE TREAT RECE	IVED		
SHOOT OR ACIDIZE			
REPAIR WELL SEP 14	1002 E: Report results of multiple completion or zone		
PULL OR ALTER CASING MULTIPLE COMPLETE MULTIPLE COMPLETE	change on Form 9-330.)		
CHANGE ZONES U. S. GEOLOGI	CAL SURVEY		
ABANDON* FARMINGTO	H, N. M.		
(other) X - Set Cement Plug			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	irectionally drilled, give subsurface locations and		
ARCO hereby asks permission to set a cerinterval (1464-1600' OA) in the subject with the requirements as set forth in a 1981, and a subsequent letter of April 2 of New Mexico, Energy and Minerals Depart Division (copies attached.)	well. This is in compliance memorandum dated September 30, 26, 1982, both from the State		
Attached is the procedure for setting the	ne cement plug.		
This Appendid for Tempor N. 10-16-83			
Subsurface Safety Valve: Manu. and Type	Set @Ft.		
18. I hereby certify that the foregoing is true and correct	and some expenses of the second		
SIGNED Stephen Rose TITLE Dist. Prod. S	Supt.DATE August 31, 1982		
S. C. ROSE			
	DATE		
CONDITIONS OF APPROVAL IF ANY:			

DISTRICT ENGINEER •See Instructions on Reverse Side

HORSESHOE GALLUP UNIT INJECTION WELLS PLUGGING PROCEDURE

- 1. MIRU.
- 2. Release packer and pull tubing and packer out of hole.
- 3. RIH with tubing open-ended to 40' above the top perforation and pump sufficient cement to set a 100' plug inside the casing (Using light-weight cement).
- 4. POH, RD, and move off.



STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

BRUCE KING ARRY KEHOE

April 26, 1982

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE. NEW MEXICO 87501 (505) 827-2434

RECEIVED

APR 30 1982

ENGINEERING

Arco Oil & Gas Company P.O. Box 5540 Denver, Colorado 80217

ATTENTION: J. G. Bradshaw

RE: Exception to Rule 705-A for Injection Wells in the Horseshoe Gallup Unit, Federal Lease No. 14-08-0001-8200, San Juan County,

New Mexico.

Dear Sir:

Pursuant to your letter of February 18, 1982, requesting exception to Rule 705-A for fifty-seven (57) wells as listed on Table I, the Oil Conservation Division hereby denies both of your requests. You are hereby requested to take prompt action as outlined in the September 30, 1981, Memorandum. (Copy enclosed).

The Oil Conservation Division will not grant an exception to Rule 705-A if a well will not be placed in service within 6 months of the request. For future reference, supportive data for exception to Rule 705-A should include:

- 1. Proof of mechanical integrity, such as bradenhead tests, tracer logs, or other supportive tests or data.
- 2. All related OCD Division Order Numbers or Case Hearing Numbers.
- 3. A schematic of the present injection well including cement tops and quantities thereof.
- 4. Date each well was shut-in.

If you have any questions regarding this matter, please do not hesitate to contact me at (505) 827-2533.

Sancerely,

JÓE D. RAME

Division Director

TABLE I

Horeshoe Gallup Unit Federal Lease No. 14-08-001-8200 San Juan County, New Mexico.

List of Wells

∔.	NO.	26	b

- 2. No. 29 B
- 3. No. 103 A
- 4. No. 105 A
- 5. No. 113 A
- 6. No. 126 C
- 7. No. 130 C
- 8. No. 132 C
- 9. No. 135 C
- 10. No. 137 C
- 11. No. 139 C
- 12. No. 141 C
- 13. No. 143 D
- 14. No. 145 D
- 15. No. 148 D
- 16. No. 150 D
- 17. No. 152 D
- 18. No. 154 D
- 19. No. 156 D
- 20. How 160 D

- 21. No. 215 D
- 22. No. 162
- 23. No. 164 D
- 24. No. 169
- 25. No. 171 D
- 26. No. 173 D
- 27. No. 175 D
- 28. NO. 190
 - 29. No. 182 D
 - 30. No. 184 D
 - 31. No. 186 🗅
- -32. No. 192 P
- 33. No. 194 D
- 34. No. 196 D
- 35. No. 201
- 36. No. 203
- 37. No. 205 D
- 38. No. 207 D
- 39. No. 213 D
- 40. No. 217 D

- 41. No. 223 D
- 42. No. 225
- 43. No. 227 D
- 44. No. 229 D
- 45. No. 238 D
- 46. No. 240 D
- 47. No. 248 D
- 48. No. 250 D
- 49. No. 259 D
- 50. No. 261 C
- 51. No. 263 C
- 52. No. 269 C
- 53. No. 274 C
- 54. No. 275 C
- 55. No. 73 A
- 56. No. 199
- 57. No. 211



FNFRGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION

POST OFFICE BOX 20 STATE LAND OFFICE BL SANTA FE, NEW MEXICO : (505) 827-2434

ARRY KEHOE SECRETARY

MEMORANDUM

TO:

ALL NEW MEXICO INJECTION WELL OPERATORS

FROM:

JOE D. RAMEY. DIRECTOR

SUBJECT:

TEMPORARY ABANDONMENT OF INJECTION WELLS

Division Rule 705A provides in part that "no injection well may be temporarily abandoned for more than six months unless . the injection interval has been isolated by use of cement or a bridge plug." The Division Director may delay the cement or bridge plug requirement upon a request by the operator and a showing that such well is mechanically sound, that there is a continuing need for the well, and that the well constitutes no threat to underground sources of drinking water.

Division survey programs have found several hundred injection wells which have not been used for at least six months and which do not have the requisite plugs. Based upon these surveys the Division will be moving to enforce Rule 705A in the near future.

Operators should review the status of their injection wells and within the next six months take one of the following actions relative to injection wells which have been shut in for six months or longer:

- Return the well to active operation. (1.)
- Plug and abandon the well or place a cement or bridge plug above the injection interval.
- File a workover or plugging plan and schedule (3) with the appropriate Division district office.
- (4) File a request for exception to Rule 705A with the Division Director in Santa Fe.

September 30, 1981 fd/