

GOVERNOR

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO B7410 (505) 334-6178

August 10, 1983

C & E Operators, Inc. 4849 Greenville Ave. Dallas Tx 75206

Re: Abrams #1, J-5-30N-11W

Gentlemen:

A recent field inspection reveals that the referenced well is leaking gas at the surface, outside the surface pipe. All vegetation on location is dead indicating gas is surfacing over a fairly large area.

You are directed to dig out around the surface pipe to check for leaks. The gas may be coming from a flow line leak. This should also be checked out. The bradenhead valve is leaking salt water and should be changed. Please initiate this action as soon as possible.

Yours truly,

Charles Gholson

Deputy Oil and Gas Inspector

CG/lh

cc: Dick Stamets

Reading File Well File Operator File

Lonnie Cunningham, Geolectric, Aztec