

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-6996

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Owen

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Verde Gallup

11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA

Sec. 6, T30N, R15W

12. COUNTY OR PARISH

San Juan

13. STATE

N. Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

M. MARTIN OIL & GAS CO.

3. ADDRESS OF OPERATOR

4705 N. 32nd PLACE, PHOENIX, ARIZONA

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1870' from the South line and 620' from the West line of Section 6, T30N, R15W, San Juan County, New Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5430 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned in the following manner on Aug. 20, 1965.

Pulled rods, tubing and pump.


Shot 4 1/2" production casing off at 1240' from surface and pulled from hole.

Pumped 35 sacks of cement through tubing and plugged open hole.

Pumped 25 sacks of cement through tubing and placed plug 50' in and 50' out of pipe stub. (Top of pipe stub is 1240' below ground level.)

Pumped 10 sacks of cement through tubing and placed plug at surface. Imbedded steel marker in cement at surface with name and location of well stenciled there on.

Cleaned location.



18. I hereby certify that the foregoing is true and correct

SIGNED

E. A. Clement

TITLE Agent for M. Martin

DATE 8/24/65

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE