

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Antelope
Lease No. 278200
Unit 1-00

RECEIVED

MAY 7 1952

SUNDRY NOTICES AND REPORTS ON WELLS OIL CON. COM.
DIST. 3

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 1650 ft. from N line and 940 ft. from E line of sec. 1
(1-30-10)
18-30 sec. 1 30 10 Antelope
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6569 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

April 30, 1952 Ran 26 joints of 7" OD 23 1/2 lb. rd. thd. 1-55 new casing. (1127.49',
Ran 59 joints 7" OD 20 lb. rd. thd. 1-55 new casing. (3751.51') Set at 4279' and
Barkin float collar and guide shoe. Float up 1 joint, 45.72'.

Well to be cemented with 675 sacks. 5 sacks of neat cement on top,
to facilitate temperature survey, 640 sacks Bridget cement, and 30 sacks of neat
around bottom of casing. Mixed 5 sacks neat, and 627 sacks Bridget, (this consisting
of 612 con. cement, 66 gal. 33% Perlite) and pressure ran up to 1200 psi; 2500 psi
was applied and could not move cement. Drilled cement out of casing.

May 4, '52. Cemented with 100 sacks common cement, 81 feet left in casing,
no returns. Plug down 7 p.m.

May 5, '52 Ran temperature survey 7 a.m. indicated filled up back of casing
to 4325 feet.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Barry Oil Corporation

Address Box 96, Aztec, New Mexico

By _____

Title Group Foreman

100-443890-1
 NOV 21 1960
 MAR 22 1961
 COMMUNICATIONS
 DIVISION
 U.S. DEPT. OF JUSTICE

[illegible]

100

..... $\left(\frac{1}{2} \right)$ has an $\left(\frac{1}{2} \right)$ below it

$\frac{1}{\sqrt{2}} \begin{pmatrix} 1 & i \\ 0 & 1 \end{pmatrix}$

(700/100/11-11-11) (100/100/11-11-11) (100/100/11-11-11)

..th a lot I saw ovoids rock bluish out to redish and

2007-00-000000

1. The following information is provided for the year ended 31 December 2014:

I am sending this plan of work must receive at least a meeting of the Geological Survey and the Department of the Interior.

2000

[illegible]

5.

202