	SUBMIT IN TRIPLICATE.	Form approved. Budget Bureau No. 42-R14:
DEPARTMENT OF THE INTERIOR	OR (Other instructions on reverse side)	5. LEASE DESIGNATION AND SERIAL NO
GEOLOGICAL SURVEY		14-20-603-4904
SUNDRY NOTICES AND REPORTS C		6. IF INDIAN, ALLOTTEE OR TRIBE NAM
(Do not use this form for proposals to drill or to deepen or plug buge "APPLICATION FOR PERMIT" for such pr	ack to a different reservoir. oposals.)	Save ia
		7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER		
NAME OF OPERATOR		8. FARM OR LEASE NAME
Ncculloch Oil Corp. of California		9. WELL NO.
Box 234, Farmington, H. H.		
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT
		Yerde Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
27.071 au 19.000 Au 1		Sec 1 Tam 9159
PERMIT NO. 15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
5500' D.F.		San June H. M.
Check Appropriate Box To Indicate N	lature of Notice, Report, or C	ther Data
NOTICE OF INTENTION TO:		ENT REPORT OF:
	WARR CHES OFF	REPAIRING WELL
TEST WATER SHUT-OFF PULL OR ALTER CASING PLANT MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL CHANGE PLANS	(Other)	
(Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent)	Completion or Recompl	of multiple completion on Well etion Report and Log form.)
 Spotted 24 sx. cement plug 1550° to T.I Stuck tbg. unable to pull; backed off the bala 		remai nder of tbg. in
Stuck the unable to pull; backed off the hole.		resalader of the. la
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 		FELLEN
Stuck the unable to pull; backed off the hole.		FELLEN
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 		FELLEN
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 		FELLEN
 Stuck thg. unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 		FELLEN
 Stuck thg. unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 		FELLEN
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 	two jts. down - left	FELLEN
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 		FELLEN
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 	two jts. down - left	TOTAL TOTAL
 Stuck thg. unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 	two jts. down - left	FELLEN
 Stuck the unable to pull; backed off the hole. Spotted 10 sx. cament at surface. 	two jts. down - left	FELLEN
2. Stuck the mable to pull; backed off the hole. 3. Spotted 10 sx. cament at surface. 4. Installed dry hole marker. Thereby certify that the foregoing is true and correct Original attentions.	bio jts. dom - left	DEC 13 1968 OEC 13 1968 OEC 13 1968
 Stuck thg. unable to pull; backed off the hole. Spotted 10 sx. cament at surface. Installed dry hole marker. I hereby certify that the foregoing is true and correct	two jts. down - left	DEC 13 1968 CON. COM.