

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

RECEIVED
BLM

98 JUN 15 PM 12:31

070-173-1000-1, NM

1. Type of Well
OIL

2. Name of Operator
King Oil

3. Address & Phone No. of Operator

Location of Well, Footage, Sec., T, R, M

1650' FNL and 990' FEL.; Unit H, Sec. 5, T-30-N, R-17-W,

5. Lease Number
14-20-603-2021

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Joella #1

9. API Well No.
30-045-09997

10. Field and Pool

11. County & State
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service Inc., as contractor, re- entered and then plugged and abandon this well per the attached report.

This work was done on an emergency basis for the NMOCD Aztec District Office.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 6/11/98

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

FARMINGTON DISTRICT OFFICE

NMOCD

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

RECEIVED
BLM

May 28, 1998

98 JUN 15 PM 12:31

070 FARMINGTON, NM

Oil Conservation Division
State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410

Re: Plug & Abandonment Report **Joella X #1 Well**
NE, 5, 30N, 17W
San Juan County, NM

Cementing Summary:

Plug #1 with 47 sxs Class B cement from 469' to 60' to fill open hole and 5-1/2" casing.

Plug #2 with 70 sxs Class B cement inside 5-1/2" casing from 60' to surface, squeezed 53 sxs outside casing.

Plugging Summary:

- 5-26-98 Road rig and equipment to location. Safety Meeting. RU rig and equipment. Note 5-1/2" casing collar had previously been welded onto casing stub. Layout relief line to pit. Check well pressure: casing 20#, bleed well down. NU BOP and test. PU 4 3/4" bit and 2 - 3-1/8" drill collars and TIH with 13 joints 2-3/8" A-Plus workstring. Tag bottom at 470'. Establish circulation with 10 bbls water. Plug #1 with 47 sxs Class B cement from 469' to 60' to fill open hole and 5-1/2" casing. POH and LD tubing, drill collars and bit. RIH with 2 joints tubing and circulate hole clean to 61'. POH. Shut in well and WOC. SDFD.
- 5-27-98 Safety Meeting. RU A-Plus wireline truck. RIH and tag cement at 116'. Perforate 3 1-11/16" squeeze holes at 60'. Pump 10 bbls water to attempt to circulate outside 5-1/2" casing to surface; did not circulate to surface. Plug #2 with 70 sxs Class B cement inside 5-1/2" casing from 60' to surface, squeezed 53 sxs outside casing. RD rig and equipment; move off location.
- 5-28-98 Found cement at surface in 5-1/2" casing. Mix 10 sxs Class B cement and install P&A marker. Job Complete
J. Sanchez, BLM Representative was on location 5-27-98.
G. Jones, A-Plus Well Service was on location.