

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee Bole-Lin-Choo-Sagay  
Lease No. 14-22-222-4204

X		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED  
FEB 1 1961  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

January 18, 1961

Well No. Indian 2-1 is located 600 ft. from N line and 1200 ft. from W line of sec. 1  
22 N 1 E 1 T 20 N R 16 W 1200 (Meridian)  
(Twp.) (Range)  
Horseshoe Mt San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5404 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On Jan. 9, a cable tool unit was rigged up on the location, and the 4" F.J. Liner was pulled from the well. The open hole was then cleaned out to TD w/cable tools. The hole was then treated w/1000 gal. 15% HCl acid w/ H-20 additive. Tg. was then run & the acid swabbed out. Well was then placed back on prod.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Compas Exploration, Inc.

Address 1045 Court Place  
Denver 2, Colorado

By R. Farrelly  
Title Chief Geologist