	,
NO. OF COPIES RECEIVED	Form C-103
DISTRIBUTION	Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	
U.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State XX Fee.
OPERATOR 3	5. State Oil & Gas Lease No.
	E-1196-3
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
El Paso Natural Gas Company	EPNG Com "A"
3. Address of Operator	9. Well No.
P. O. Box 990, Farmington, New Mexico	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER M 890 FEET FROM THE South LINE AND 1120 FEET FROM	Blanco Mesa Verde
West 32 31N 8W	
THE West LINE, SECTION 32 TOWNSHIP 31N RANGE 8W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
All	San Juan
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.  PULL OR ALTER CASING CASING CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S	PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.  PULL OR ALTER CASING CASING CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING  CHANGE PLANS  CASING TEST AND CEMENT JQB OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	hut off & Frac X
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE BULLET 1705.	hut off & Frac X
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c	estimated date of starting any proposed
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  Squeeze, Water S  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c  w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed	estimated date of starting any proposed
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c  w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.	estimated date of starting any proposed thru perfs w/125 sks.
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510' s	estimated date of starting any proposed thru perfs w/125 sks.
TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1705.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c  w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510' s  cement. WOC 18 hrs. tested w/4000#, O.K.	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze, Water S  OTHER 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c  w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed  cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510' s  cement. WOC 18 hrs. tested w/4000#, O.K.  On 12-10-66: Perf Lower Point Lookout 5236-40,5270-74,5294-98,5342-46,5	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.  1393-97,5446-52 w/12 SPZ
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c  w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510's cement. WOC 18 hrs. tested w/4000#, O.K.  On 12-10-66: Perf Lower Point Lookout 5236-40,5270-74,5294-98,5342-46,5  Frac w/17,500# 20/40 sand, 25,200 gal water. Max pr 4100#, BDP 3500#, t	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.  1393-97,5446-52 w/12 SPZ or pr 3000-3300-4100#. I
TEMPORARILY ABANDON PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) see Rule 170s.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c  w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510' s  cement. WOC 18 hrs. tested w/4000#, O.K.  On 12-10-66: Perf Lower Point Lookout 5236-40,5270-74,5294-98,5342-46,5  Frac w/17,500# 20/40 sand, 25,200 gal water. Max pr 4100#, BDP 3500#, t  47 BPM, dropped 4 sets of 12 balls each, flushed, ISIP zero. Set BP @ 5	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.  393-97,5446-52 w/12 SPZ or pr 3000-3300-4100#. If 229', tested w/4500#,0K
TEMPORARILY ABANDON PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) see RULE'1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. c w/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510' s cement. WOC 18 hrs. tested w/4000#, O.K.  On 12-10-66: Perf Lower Point Lookout 5236-40,5270-74,5294-98,5342-46,5 Frac w/17,500# 20/40 sand, 25,200 gal water. Max pr 4100#, BDP 3500#, t 47 BPM, dropped 4 sets of 12 balls each, flushed, ISIP zero. Set BP @ 5 Perf Point Lookout 5113-19,5154-60,5201-13 w/18 SPZ. Frac w/40,000# 20/	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.  et at 5520' w/125 sks.  et at 5520' w/125 sks.  2393-97,5446-52 w/12 SPZ  ar pr 3000-3300-4100#. II  229', tested w/4500#, OK
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.  12-3-66: Cut stuck tubing at 4692', left 608' fish in open hole.  12-4-66: Set cement retainer at 4445', squeezed open hole w/200 sks. cw/1000#. Perf 3 squeeze holes at 1755', set retainer at 1645'. Squeezed cement. tested perfs w/800#, O.K.  12-9-66: T.D. 5520', ran 172 joints 4 1/2", 10.5#, J-55 casing 5510' s cement. WOC 18 hrs. tested w/4000#, O.K.  On 12-10-66: Perf Lower Point Lookout 5236-40,5270-74,5294-98,5342-46,5  Frac w/17,500# 20/40 sand, 25,200 gal water. Max pr 4100#, BDP 3500#, t 47 BPM, dropped 4 sets of 12 balls each, flushed, ISIP zero. Set BP @ 5  Perf Point Lookout 5113-19,5154-60,5201-13 w/18 SPZ. Frac w/40,000# 20/  water. Max pr 3200#, BDP 2700#, tr pr 2700-2750-3200#. IR 55 BPM, dropped	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.  et at 5520' w/125 sks.  et at 5520' w/125 sks.  2393-97,5446-52 w/12 SPZ  er pr 3000-3300-4100#. If 229', tested w/4500#,0K
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks. et at 5520' w/125 sks. et at
TEMPORARILY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER Squeeze, Water S  OTHER Squeeze	estimated date of starting any proposed thru perfs w/125 sks.  et at 5520' w/125 sks.  et at 5520' w/125 sks.  et at 5520' w/125 sks.  229', tested w/4500#, OK 40 sand, 40,000 gallons ed 2 sets of 18 balls iff House 4712-26, pr 3200#, BDP 3200#,

TITLE Petroleum Engineer

SUPERVISOR DIST. #3

DEC 20 1986.

Original Signed F. H. WOOD

Original Signed by Emery C. Arnold