Form 9-331 (May 1963)

## UNITED STATES

SUBMIT IN TRIPLICATE\*
(Other instructions on re-

Form approved. Budget Bureau No. 42-R1424.

DEPART	MENT OF THE INTERIOR verse side)	5. LEASE DESIGNATION A	NO SERIAL NO.		
	GEOLOGICAL SURVEY	SF-079037 /	OD TRIVE VALUE		
(Do not use this form for prot	TICES AND REPORTS ON WELLS  losals to drill or to deepen or plug back to a different reservoir.  CATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME		
1.		7. UNIT AGREEMENT NAM	TE.		
OIL GAS X OTHER					
2. NAME OF OPERATOR	8. FARM OR LEASE NAME	E			
Aztec Oil & Gas Compa	Hale				
3. ADDRESS OF OPERATOR	9. WELL NO.				
P.O. Drawer 570. Far	mington, New Mexico 87401	#4			
4. LOCATION OF WELL (Report location See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde				
At surface	Basin Dakota				
2055' FNL -	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA				
		Section 34,T31N,R8W			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE		
	6211' GL	San Juan	New Mexico		
16. Check A	Appropriate Box To Indicate Nature of Notice, Report, o	r Other Data			

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF.					
			r	1	<del></del>	) <u> </u>	
TEST WATER SHUT-OFF		PULL OR ALTER CASING			WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE			FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*	<u>X</u>		SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS			(Other) Report results	of multiple completion on Well	
(Other)			<u> </u>		Completion or Recomple	of multiple completion on Well etion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

## PURPOSE TO:

- Pull tubing.
- Run casing scraper to 7400'. 2.
- Set cement retainer at 7400'. 3.
- Squeeze Dakota perfs with 50 sacks cement. 4.
- Run tubing and land at approximately 5450'.

## RECEIVED

AUG 23 1977

U. S. GEOLOGICAL SURVEY

	<b>'</b> )								
18. I hereby certify that the foregoing is true and SIGNED	correct	TITLE	District	Production	Manager	DATE	August	25,	1977
(This space for Federal or State office use)									
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:		TITLE				DATE			