

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

August 12, 1966

Southern Union Production Co.
P. O. Box 808
Farmington, New Mexico

Attention : Mr. Bill Vanderslice

Dear Sir:

The bradenhead test which was conducted on your #4 Quinn well, located A-19-31N-8W, on August 9, 1966 indicates that there is communication between the production casing and the surface casing. It is evident from the test that the production casing has failed. We are therefore directing that immediate remedial action be taken to repair the production casing in this well.

Very truly yours,

Emery C. Arnold
Supervisor District #3

ECA:mc

10/1/80

10/1/80

10/1/80

10/1/80

10/1/80

10/1/80

10/1/80

10/1/80