

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

Workover X

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Farmington, New Mexico

September 19, 1961

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

El Paso Natural Gas Company San Juan 32-9 U.S.A. Well No. 23 in (Unit M)
SW (40-acre Subdivision) 1/4 of Sec. 5, T. 31-N, R. 9-W, NMPM., Blanco Mesa Verde Pool
County.

San Juan

FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

It is intended to workover this well as follows:

1. Set at 2" tubing choke at approximately 5840'.
2. Move rig in and rig up, install blow-out preventer.
3. Pull tubing.
4. Run McCullough's Casing Survey.
5. Set drillable magnesium bridge plug at approximately 3500'.
6. By use of Fullbore packer, determine location of casing leak.
7. Use sufficient volume of Trinity Inferno cement, tailing in with 50 sks regular cement with 2% calcium chloride, to circulate cement to surface. W.O.C. 18 hours.
8. Drill cement and test casing with 2000#.
9. Drill bridge plug and clean out to total depth (5906') using gas and 6 1/4" bit.
10. Run temperature log.
11. Run 4 1/2" casing with a Burns liner hanger without seal.
12. Cement with 100 sks regular, 1/4 cu.ft fine Gilsonite, 4% gel, 1/3 Flocele. W.O.C. 18 hours.

Approved..... 9-22, 1961 (OVER)
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....
Title Supervisor Dist. # 3

Original Signed D.W. McEnany
El Paso Natural Gas Company

By.....

Position.....

Send Return to Engineer well to:

Name..... E. S. Oberly

Address..... Box 990, Farmington, New Mexico



13. Clean out to top of liner. Best with 2000#.
14. Clean out to a C.O.T.D. according to perforating log.
15. Perforate and fracture as per log.
16. Clean out to C.O.T.D. and test.
17. Run tubing and complete.
18. Clean location and release rig.

STATE OF NEW MEXICO	
OIL CONSERVATION COMMISSION	
AZTEC DISTRICT OFFICE	
NUMBER OF COPIES RECEIVED	
DATE	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	