Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALLOG LAND MANAGEMENT

RECEIVED BLM FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

. Lease Designation and Serial No.

BUREAU OF L	AND MANAGEMENT	5. Lease Designation and Serial No.
CUNIDDY MOTICES AN	D PEDODES ON WELLS NIC 15 AM 9: AL	SF-079029
SUNDRY NOTICES AND REPORTS ON WELLS AUG 5 AH 9: 04 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name
DO NOT use this form for proposals to dring	PERMIT - " for such propesale ADMINGTON NM	
USE AFFLICATION TON	TEMMIT TO SEEN PROPERTY THE TOTAL THE TANK	7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		
1. Type of Well		San Juan 32-8 Unit
Oil X Gas Well Other		8. Well Name and No.
2. Name of Operator		SJ 32-8 #20
Phillips Petroleum Company		9. API Well No.
3. Address and Telephone No.		30-045-11025
5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454		10. Field and Pool, or exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Blanco Mesaverde
Unit(L) 1560' FSL & 910' FWL Section 4, T31N, R8W		11. County or Parish, State
Section 4, ISIN, ROW		San Juan, NM
The second secon) TO INDICATE MATURE OF NOTICE REPORT	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
M House of many	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
<u> </u>	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other Sidetrack	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
MIRU Rig. Set BPV in tubing hanger. ND WH, NU BOP & Test. Pull BPV. Pull tubing. RIH with 7" cement retainer and set @ +/- 5100'. Pump 1 casing/OH volume of cement below retainer. Leave 50' cement on top of retainer. RIH w/CIBP & set @ +/- 3200'. RIH and set oriented whipstock on top of CIBP. RIH w/casing mill and mill window in casing. RIH w/directional tools and orient tools. Kickoff & drill directional hole w/gas. POOH w/directional tools, PU rotary stablized assembly & gas drill to TD (approx. 5900'). Run & cement 4-1/2" casing with at least 100' cement inside 7" casing. Run temperature survey to locate top of cement. Test 4-1/2" casing to 1500 psi. Run GR/N/CCL. Perforate HV.—Acidize with 1500 gals. 15% HCl & balls. Sand frac MV (Single-Stage). Flowback. Cleanout to PBTD. Land tubing @ top of Pt. Lookout. Return well to production. Note: A workover pit may be required.		
of the state of correct		ao Follo
14. I hereby certify that the foregoing is true and correct Signed	Title Envir./Regulatory Engineer	Date 8-15-96
(This space for Federal or State office use)	— Superior of manager (s)	
Approved by	Title	Date
Conditions of approval, if any:		
		<u> </u>
Title 18 U.S.C. Section 1001, makes it a crime for any perso or representations as to any matter within its jurisdiction.	n knowingly and willfully to make to any department or agency of the Uni	ted States any talse, fictitious or traudulent statements
or representations as to any matter within its jurisdiction.		