

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. 14-25-312-112
2. NAME OF OPERATOR Thomas A. Dwyer	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 224, Farmington, N. M.	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FWL 750' FWL	8. FARM OR LEASE NAME Shiela
14. PERMIT NO.	9. WELL NO. 3
15. ELEVATIONS (Show whether DE, RT, CR, etc.) 441' ASL	10. FIELD AND POOL, OR WILDCAT Wildcat
	11. SEC., T., R., M., OR BLM. AND SURVEY OR ALTA 14-311-112
	12. COUNTY OR PARISH 13. STATE San Juan New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/9/66 Moved in cable tool rig - drilled 7" hole 50' - set 50' 5 1/2" O.D. 1 1/2" casing. Cemented with 4 sx.

10/10/66 Moved in rotary rig.

10/11/66 Drilled 4 3/4" hole to 995' - Ran Crane Electric log - started in hole with drill pipe. Well blow out. Pulled drill pipe. Ran Crane log - determined gas coming from Tooto formation at 385'. Put swedge in surface casing. Well gauged 750 MCF with no water.

10/13/66 Well gauged 700 MCF w/no water after blowing 98 hours. Ran 2 7/8" O.D. 5.4# J-55 SR EUE tubing set at 995', cemented w/80 sx neat. P.O.B. 9:00 P.M. 10-18-66.

10/25/66 Drilled 2 1/4" hole to 1028' - Top Dakota 1012'

10/26/66 Hole flowing sulfur water - no show oil. laid down 1 1/4" tbg. Shut well in.

18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dwyer TITLE Eng. DATE 11-25-66

(This space for Federal or State use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

RECEIVED
NOV 28 1966
OIL CON. COM.
DIST. 3

RECEIVED
NOV 25 1966