

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.
14-20-603-2027

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jeb

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Tlick Rock Dakota

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 30, T30N, R17W

12. COUNTY OR PARISH 13. STATE
Cottonwood N.M.

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
W. M. Galloway

3. ADDRESS OF OPERATOR
Box 2, Petroleum Plaza Bldg., Burlington, N.J. 07401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 175' 111, 35' 132

11. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
1. STOP WATER SHUT-OFF <input type="checkbox"/>	2. PLUG OR ALTER CASING <input type="checkbox"/>	3. WATER SHUT-OFF <input type="checkbox"/>	4. REPAIRING WELL <input type="checkbox"/>
5. FAILURE TREAT <input type="checkbox"/>	6. MULTIPLE COMPLETION <input type="checkbox"/>	7. FRACTURE TREATMENT <input type="checkbox"/>	8. ALTERING CASING <input type="checkbox"/>
9. SHOOT OR ACIDIZE <input type="checkbox"/>	10. ABANDON* <input type="checkbox"/>	11. SHOOTING OR ACIDIZING <input type="checkbox"/>	12. ABANDONMENT* <input type="checkbox"/>
13. REPAIR WELL <input type="checkbox"/>	14. CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ones in well no longer capable of producing...

170' to 210'

700' to 707'



170' cemented to surface.

All plugs to be set with 2 3/8" upset casing.

Set cement plug inside 4 1/2" casing 700' to I.D. of 707'

Set plug in surface.

Set 4 1/4" marker.



18. I hereby certify that the foregoing is true and correct

SIGNED W. M. Galloway TITLE Geologist DATE May 31, 1972

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.