

6 BLM 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM 030555 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Mexico Federal "L"

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10, T30N, R13W, NMP

12. COUNTY OR PARISH
San Juan

13. STATE
NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P & A

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FSL - 1650' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

5703' GL 5713' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Request BLM Inspection

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As indicated in the approved Application for Permit to Drill, under Environmental Stipulations, Section 3: Reseeding and Abandonment - Subparagraph C: "If in the opinion of the surface management agency" (in this case the BLM), "the seeding is unsuccessful, the lessee/operator may be required to make subsequent seedings". The recommended method of seeding explained under the same Section 3, subparagraph B was performed August 29, 1986 for the No. 1 Mexico Federal "L" & the No. 1 Dare Devil locations. Surface restoration has been completed and is now ready for BLM inspection.

RECEIVED

AUG 18 1986

OIL CONTROL

ASSIGNED FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan
Sherman E. Dugan

TITLE

Geologist

DATE 8-8-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

AUG 15 1986

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

BY

ah

NMOCC

*See Instructions on Reverse Side