

RIJAN OIL COMPANY, INC.

Korber Building
ALBUQUERQUE, NEW MEXICO 87101


October 7, 1968

Mr. Emery C. Arnold
Supervisor, Oil & Gas Commission
1000 Rio Brazos Road
Aztec, New Mexico


Dear Sir:

In compliance with the Oil Conservation Commission Rule No. 111, straight hole deviation tests were made on our No. 8 Rijan well while drilling. The No. 8 Rijan well is located 640' FSL and 165' FWL in Sec. 31 of Twp. 30N, Range 16W, San Juan County, New Mexico. One test was taken September 23, 1968 at 400' while drilling and was off $\frac{1}{2}$ degree from vertical. A second test was made at 715' and was off $1\frac{1}{4}$ of a degree from vertical on September 25, 1968. Hole depth is 783.5' feet.

Yours truly,


Val R. Reese, Geologist
Rijan Oil Company

Subscribed and sworn to before me this 6th day of
October 1968.


Notary Public

My commission expires May 10, 1970.

