

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	3004520381
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Jacques Com A
8. Well No.	1
9. Pool name or Wildcat	Blanco PC
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	5646' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator AMOCO PRODUCTION COMPANY
3. Address of Operator P.O. Box 800 Denver Co 80201	4. Well Location Unit Letter M : 990 Feet From The South Line and 990 Feet From The West Line Section 25 Township 30N Range 9W NMPM SAN JUAN County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5646' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company intends to plug and abandon the subject well.
See attached for procedure:

If you have any questions please call Julie Acevedo at 303-830-6003.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Julie Acevedo TITLE Sr. Staff Assistant DATE 09 29 1992
TYPE OR PRINT NAME Julie Acevedo TELEPHONE NO. (303) 830-6003

(This space for State Use)

APPROVED BY Original Signed by CHARLES GHOLSON TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DELETE STEP 3

Plug and Abandonment Procedure


Jacques Com A 1

25M - T30N - R9W

1. MIRUSU. NDWH. NUBOPE.
2. Unset and retrieve Model C-1 packer.
3. Fill hole with 9 ppg mud.
4. Run CBL from TD to surface.
5. TIH w/ tubing and cement retainer. Set retainer at 2280. Squeeze perforations with 20 cu. ft. cement. Sting out of retainer and spot cement plugs to TOC found by CBL. WOC.
6. Locate csg leak(s).
7. Contact Amoco's San Juan Operations Center for further instructions.

Note: Use Class G neat cement.

JACQUES COM A 001 122
 Location - 25M-30N-9W
 Blanco Piedrad Cliffs
 Original Completion - 3/69
 Last File Update - 2/90



Braden head squeeze of 100 ax to kill gas flow (2/89).