

DISTRICT I
P.O. Box 1280, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 60, Arteria, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Altec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30 045 20381

3. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OR

WELL ☐

OAS

WELL ☒

OTHER

2. Name of Operator

Amoco Production Company Attn: John Hampton

3. Address of Operator

P.O. Box 800, Denver, Colorado 80201

4. Well Location

Unit Letter M : 990 Feet From The South Line and 990 Feet From The West Line

Section 25

Township 30N

Range 9W

NMNM

San Juan

County

10. Elevation (Show whether OF, RKB, RT, OR, etc.)

5646' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company intends to plug and abandon the subject well.
See attached for procedure:

If you have any questions please call Julie Acevedo at 303-830-6003

RECEIVED

MAY 09 1990

OIL CON. DIV.

DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

John Hampton

TITLE

Sr. Staff Admin. Supv. DATE 5/7/90

TYPE OR PRINT NAME

John Hampton

TELEPHONE NO.

(This space for State Use)

Original Signed by CHARLES GHOLSON

APPROVED BY

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

MAY 09 1990

COORDINATOR OF APPROVAL, IF ANY:

[illegible]

0221 20 YAM

10. 11. 2014

Plug and Abandonment Procedure
Jacques Com A 1
25M - T30N - R9W

1. MIRUSU. NDWH. NUBOPE.
2. Unset and retrieve Model C-1 packer.
3. ~~Fill hole with 9 ppg mud.~~
4. Run CBL from TD to surface.
5. TIH w/ tubing and cement retainer. Set retainer at 2280.
Squeeze perforations with 20 cu. ft. cement. Sting out of
retainer and spot cement plugs to TOC found by CBL. WOC.
6. Locate csg leak(s).
7. Contact Amoco's San Juan Operations Center for further
instructions.

Note: Use Class G neat cement.

JACQUES COM A 001 122
Location - 25M-30N-9W
Blanco Pictured Cliffs
Original Completion - 3/69
Last File Update - 2/90

