## UNITED STATES

## BUREAU OF LAND MANAGEMENT BLM

Sundry Noti			
	ces and Reports on Weld	<b>#</b> 1:37	
Type of Well	070 FARMING	TON, NM 5.	Lease Number SF-078129 If Indian, All. or
GAS	,		Tribe Name
Name of Operator		7.	Unit Agreement Name
BURLINGTON	GAS COMPANY	EWED	
5.0		V 1 1 1999 🐕	Well Name & Number Pierce #6
Address & Phone No. of Operat PO Box 4289, Farmington, NM	87499 (505) 326-9 <b>70</b> 0		API Well No. 30-045-20469
Location of Well, Footage, Se		NT. 3 10	Field and Pool
1720'FNL 1840'FEL, Sec.17, T-	30-N, R-9-W, NMPM	11	Blanco Pictured Clif County and State San Juan Co, NM
2. CHECK APPROPRIATE BOX TO INI			R DATA
Type of Submission	Type of Act	<b>cion</b> Change of Pi	land
_X_ Notice of Intent		Change of F	
Subsequent Report	Plugging Back _	Non-Routine Water Shut	Fracturing
Final Abandonment	Casing Repair Altering Casing _ _X_ Other - restimula	Conversion	
	loted Operations		
3. Describe Proposed or Comp.	reced Operacions		
It is intended to restimuting the following materials.	late the Pictured Cliff	s formation of	the subject well
It is intended to restimu in the following mull 1 1/2" tubing.	late the Pictured Cliff nanner: Clean out to plug back treat the Pictured Clif	total depth at	: 3029'. Acidize
It is intended to restimu in the following m Pull 1 ½" tubing. and foam fracture	late the Pictured Cliff nanner: Clean out to plug back treat the Pictured Clif	total depth at	: 3029'. Acidize
It is intended to restimu in the following m Pull 1 ½" tubing. and foam fracture	late the Pictured Cliff nanner: Clean out to plug back treat the Pictured Clif	total depth at	: 3029'. Acidize
It is intended to restimu in the following mult 1 ½" tubing.  and foam fracture well to production	late the Pictured Cliff nanner: Clean out to plug back treat the Pictured Clif	total depth at	: 3029'. Acidize
It is intended to restimu in the following mull 1 %" tubing.  and foam fracture well to production	late the Pictured Cliff nanner: Clean out to plug back treat the Pictured Clif	total depth at	: 3029'. Acidize
It is intended to restimu in the following multiple following multiple following multiple following and foam fracture well to production well to production for following for the following multiple for the follo	late the Pictured Cliff nanner: Clean out to plug back treat the Pictured Clif	total depth at fs zone. Clear	: 3029'. Acidize
It is intended to restimu in the following must be following must be followed and foam fracture well to production well to production.  4. I hereby certify that the igned was ball build.  This space for Federal or State	late the Pictured Cliff nanner:  Clean out to plug back treat the Pictured Cliff.  foregoing is true and  (MDW) Title Regulatory e Office use)	total depth at fs zone. Clear	2 3029'. Acidize on out and return
It is intended to restimu in the following multiple following multiple following multiple following and foam fracture well to production well to production for following for the following multiple for the follo	late the Pictured Cliff nanner:  Clean out to plug back treat the Pictured Cliff.  foregoing is true and  (MDW) Title Regulatory e Office use)	total depth at fs zone. Clear	2 3029'. Acidize of out and return