APPROVED BY

CONDITION OF APPROVAL, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OIL COM, E.Y.

		BUREAU	OF LAND MANAG	EMENT			DIST. 3	
		Sundry No	tices and Repo	rts on Well	S			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					5.	Lease Number SF-078125	
!	Type of Wel GAS	.1		. (2		б.	If Indian, All. or Tribe Name	
						7.	Unit Agreement Name	
I	Name of Ope MERIDI							
3. 1	Address & P	Phone No. of Oper	ator			8.	Well Name & Number Sunray A #3	
		39, Farmington, N		326-9700		9.	-	
		Well, Footage,		· · · · · · · · · · · · · · · · · · ·		10.	Field and Pool	
	1750'FNL, 1	.840'FWL, Sec.15,	T-30-N, R-10-	W, NMPM		11.	Blanco Pictured Cliffs County and State San Juan Co, NM	
	CHECK ADDR	ROPRIATE BOX TO I	ATT COMP NAMED IN	05 11057.55				
	X_ Sub	cice of Intent osequent Report nal Abandonment	Pluggin X Casing Alterin Cther -	etion g Back Repair g Casing	Water Si	struct tine I nut or	tion Fracturing	
13.	Describe	Proposed or Com	pleted Operati	ons				
	2-24-95 2-25-95	MIRU. ND WH. NU BOP. TOOH w/97 jts 1 1/4" tbg. Dump 7 sx sd down 2 7/8" csg, let settle across perfs. SDON. TIH, tag sd @ 3011'. Perfs @ 3088'. Load hole w/wtr. TOOH. Isolate csg leak @ 275'. Establish circ through bradenhead. Pump 125 sx Class "B" cmt w/2% calcium chloride. Circ 10 bbl cmt to surface. Close bradenhead valve. Displace w/2.5 bbl wtr. SI. WOC.						
	2-26-95	2-26-95 TIH to 800'. PT csg, no test. Establish injection. TOOH. Try to establish circ through bradenhead, could not. RU, pump 75 sx Class "B" cmt w/2% calcium chloride. Sqz locked up. Left 275' cmt in csg. WOC. Circ out top 150' cmt. Re-pressure csg to 500 psi, SI. SDON.						
	2-27-95							
	2-28-95	TOOH, RIH w/96 RD, Rig relea:	jts 1 1/4" 2.3	# J-55 IJ t	bg, landed	d @ 32	226'. ND BOP. NU WU.	
4./	I hereby	certify that th	e foregoing is	true and c	orrect.			
igų	ned MALL	Drapul	Title Reg	ulatory Aff	airs Dat	te 2,	/28/95	
Th:	is space fo	or Federal or Sta	te Office use)					

MAR 02 1905

-ACCEPTED FOR DECORD

Title

Date