NO. OF COPIES RECEIVED	3	Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	1/1/	5a. Indicate Type of Lease
U.S.G.S.	 	State Fee X
OPERATOR		5. State Oil & Gas Lease No.
OFERRIOR		
(DO NOT USE THIS FO	SUNDRY NOTICES AND REPORTS ON WELLS RM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. **APPLICATION FOR PERMIT -** (FORM C-101) FOR SUCH PREPOSALS.)	
I. OIL GAS WELL WEL	X OTHER-	7. Unit Agreement Name
2. Name of Operator		8, Farm or Lease Name
	CALVIN OIL AND GAS	Kaempf
3. Addres % Minerals Farmington	Management, Inc. 501 Airport Drive	10. Field and Pool, or Wildcat
		Basin Dakota
UNIT LETTERN	. 790 FEET FROM THE SOUTH LINE AND 1450 FEET FROM	
THE West	INE, SECTION 19 TOWNSHIP 30N RANGE 11 W NMPM.	
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	5644 GR 5656 RDB	San Juan ////////
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
_		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	·
PULL OR ALTER CASING	OTHER	
OTHER		
	ompleted Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE BULE 1103.	Install BOP. Pull tubing, Set cement retainer test casing to 3500 psi, ok.	
11-12-74	Run tubing, cement squeeze below retainer w/5 w/2% CaCl. Reverse out 10 sacks. Max. Press Spot 250 gallons acid, pull tubing, perforate 6472-6478, 6430-6440, 6380-6390 with 10 holes 50 holes)	ure 3000 psi. 6556-6566, 6514-6522,
11-13-74	Sand water frac with 67252 gallons 1% KCl wat gallons CFR20 and 62000 lbs 20-40 sand. Drop 20000 gallons, rate dropped to 15 BPM when ba and re-establish injection rate. Pumped 3057 27500 lbs sand. Total sand in formation 5870 pressure 1850 psi, maximum pressure 3500 psi. 31 BPM.	ped 10 balls after lls hit . Backflow O gallons water w/ Olbs. Breakdown
	Cleanout to 6600. Land tubing at 6531 KB. F Prep. to hook-up to sales line.	low well to clean-up.
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED Tan	Area Manager Minerals Management, I	nc _{bate} 11-19-1974
Pan	Clived SUPERVISOR DIST. #3	NOV 2 (1)/3
CONDITIONS OF APPRO		