submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

<u> </u>	
Sundry Notices and Reports	on Wells
1. Type of Well GAS	<ul><li>5. Lease Number     SF-078508</li><li>6. If Indian, All.or     Tribe Name</li><li>7. Unit Agreement Name</li></ul>
<ol> <li>Name of Operator         Meridian Oil Inc.</li> <li>Address &amp; Phone No. of Operator         Box 4289, Farmington, NM 87499 (505)326-970</li> <li>Location of Well, Footage, Sec, T, R, M.         1850'N 1470'W Sec.13, T-31-N, R-9-W, NMPM</li> </ol>	8. Well Name & Number Nordhaus #1A 9. API Well No. 10.Field and Pool
Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Casing Repair	NOTICE, REPORT, OTHER DATA of Action  Change of Plans New Construction k Non-Routine Fracturing
A workover was concluded 9-12-91 to replace a The rods parted and attempts to fish failed. order to recover the rods and pump. The rods the tubing landed @ 5774'. The well was put A notice of intent was not filed prior to movintended to change the wellbore configuration	bad downhole plunger pump. The tubing was pulled in and tubing were rerun with back into production.  ing on location as it was not
14. I hereby certify that the foregoing is to Signed Many Manual (DM) Title Regulato (This space for Federal or State office use)	rue and correct  ory Affairs Date 09-30-91
m z m z n	DATE
CONDITION OF APPROVAL, IF ANY:	Sm