Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

SF-078129-A

	t .	SF-078129-A
SUNDRY NOTICES AN	D REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
not use this form for proposals to drill o	or to deepen or reentry to a different reservoir.	
Hea "APPLICATION FOR P	ERMIT—" for such proposals	
USE AFFEIGATION TOTAL		7. Af Unit or CA, Agreement Designation
CURMIT IN	TRIPLICATE	
SUDMIT II4	77117 2707.12	⊣ ′
ype of Well		a way and No
¬ Oil		8. Well Name and No.
		FLORANCE GC /J/ #16A
tame of Operator AMOCO PRODUCTION COMPANY	ATTN: E.R. NICHOLSON	9. API Well No.
		30-045-21790 .
Address and Telephone No.	(303)830-5014	10. Field and Pool, or Exploratory Area
POB 800 DENVER CO 80201		BLANCO MESAVERDE
Location of Well (Footage, Sec., T., R., M., or Survey Descri	iption)	11. County or Parish, State
· 825 FSL, 1030 FEL		SAN JUAN, NM
SEC 6-T30N-R9W UNIT	ייקיי ו	Bill Goldin, 199
	TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, THE S	
TYPE OF SUBMISSION	TYPE OF ACTION	Ν
TYPE OF SUBMISSION		Change of Plans
Notice of Intent	Abandonment	
	Recompletion	New Construction
XX Subsequent Report	Plugging Back	Non-Routine Fracturing
(177) 2 nosedneur Kebour	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	X Other CASING REPAIR	Dispose Water
	Other	(Note: Report results of multiple completion on Well
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down.	ertinent details, and give pertinent dates, including estimated date of star depths for all markers and zones pertinent to this work.)* 200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP a	-NUBOP Test BOP. OK. Set
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH- Load well w 140 BBL 2% KCL. Pressure test BP a Min. Test OK. Rel. Test Pressure. SI.	rting any proposed work. If well is directionally drilled, -NUBOP Test BOP. OK. Set at 4617', Liner top at 3232',
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP a Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOH	rting any proposed work. If well is directionally drilled, -NUBOP Test BOP. OK. Set at 4617', Liner top at 3232',
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP a Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHig.	rting any proposed work. If well is directionally drilled, -NUBOP Test BOP, OK, Set at 4617', Liner top at 3232',
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP a Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHig.	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP.
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHog. Nicholson at 303-830-5014 FEB 1 5 1933	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP.
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri If you have any questions please call E. R	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHog. Nicholson at 303-830-5014 FEB 1 5 1933	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP.
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri If you have any questions please call E. R	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHog. Nicholson at 303-830-5014 FEB 1 5 1933	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP.
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri If you have any questions please call E. R If you have any questions please call E. R Signed CThis space for Federal or State office use)	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHog. Nicholson at 303-830-5014 FEB 1 5 1933	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP.
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri If you have any questions please call E. R If you have any questions please call E. R Signed (This space for Federal or State office use)	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHing. Nicholson at 303-830-5014 FEB1 S 1933 Oli Coll. Titte L. Admin. Ama	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP. Solution 1993 FEB 10 1993
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions and you have an	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOH ig. Nicholson at 303-830-5014 FEB1 51993 OIL COLL. D. Title	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP. CCEPTED FOR RECORD FEBRUARY 1993 FARMINGION RESOURCE AREA
October 23, 1992 SIC 200 SI 4.5" TBG 2 wire line BP at 4617'. Blow well down. 7" CSG & 4.5". CSG to 650 PSI for 30 12 HR. SIN. SIC 0. SI 4.5" TBG 0. BH 0 NDBOP-NUWH. SI. Rig Down. Rel. Ri If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions please call E. R If you have any questions and you have an	200. BH 0. Kill well w 50 BBL 2% KCL. NDWH-Load well w 140 BBL 2% KCL. Pressure test BP at Min. Test OK. Rel. Test Pressure. SI. Pressure test liner top, CSG & BP at 4617'. TOHing. Nicholson at 303-830-5014 FEB1 S 1933 Oli Coll. Titte L. Admin. Ama	NUBOP Test BOP. OK. Set at 4617', Liner top at 3232', H Laying down TBG & BP. OF THE LOCK TO THE STATE OF T

17.