Form	9-331
(May	1963)

16.

## DEPARTMENT OF THE INTERIOR Other Instructions on re-

SUBMIT IN TRIPLICATE.

Form approved. Budget Bureau No. 42-R1424.

DEFAILTER OF THE HATELTION VEISE STOP)	1	LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY		SF 078129-A
SUNDRY NOTICES AND REPORTS ON WELLS	e	IF INDIAN, ALLOFTER OR TRIBE NAME

(Do not use this form for pro Use "APPI.	posals to drill or to deepen or plug back to a different reservoir. CATION FOR PERMIT" for such proposals.)			
OIL GAS WELL OTHER		7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR	8. FARM OR LEASE NAME			
Tenneco Oil C	ompany	Florance		
3. ADDRESS OF OPERATOR		9. WELL NO.		
1860 Lincoln	St., Suite 1200, Denver, Co. 80203	#14A	•	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  870' FNL and 1455' FWL		10. FIELD AND POOL, OF	R WILDCAT	
		Blanco Mesa	a Verde	
		11. SEC., T., R., M., OR B SUBVEY OR ARBA		
		Sec. 8, T30N,	R9W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6284 GL	12. COUNTY OR PARISH	13. BTATE	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON\* SHOOTING OR ACIDIZING REPAIR WELL

CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

> Lost tbg. in hole while trying to complete. Able to fish out tbg down to 3096'. We propose to correct this problem as follows:

- Set cement retainer @ 2900'. Squeeze below retainer with sufficient volume to plug hole. Spot 2 sacks above retainer.
- Cut a window in 7" casing above 4-1/2" liner, set a whipstock, redrill this well to original TD and run another 4-1/2" liner through the side-
- Complete as originally planned through the sidetracked hole.

S. I hereby certify that the foregoing is true and corre	ect	
	TITLE Div. Production Manager	DATE 13-76
(This space for Federal or State office use)	edital amerika lainut aha kalendar dibantalaha, dibanta beraga, aga pro-kelandara. Pada	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE