

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER	2. NAME OF OPERATOR Meridian Oil Inc.	3. ADDRESS OF OPERATOR Post Office Box 428, Farmington, NM 87401	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990'N, 145'W	5. PERMIT NO. 5898'GL	6. ELEVATIONS (Show whether of, to, or from, etc.) 5898'GL	7. LEASE DESIGNATION AND SERIAL NO. NM 28760	8. UNIT AGREEMENT NAME Little Federal	9. WELL NO. 3	10. FIELD AND POOL, OR WILDCAT Basin Dakota	11. SEC., T., R., M., OR S.E. AND SUBST. OR AREA Sec. 12, T-30-N, R-14-W	12. COUNTY OR PARISH N. M. P. M. San Juan NM	13. STATE
--	--	---	---	--------------------------	---	---	--	------------------	--	---	--	-----------

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREAT	☐	FRACURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

12-09-87 MOL&RU. NDWH, NU BOP. Test BOP. PU 2 3/8" tbg, removed tbg. hanger, added 1 jt. 2 3/8" tbg, tagged @ 6311'. PU to 6308', Circ w/95 bbls. 9.2# mud, lowered tbg after circ & tagged again @ 6311'. PU to 6308', spotted 35 sx & squeezed 15 sx into Dk formation. Displaced tbg, pulled 8 stds. WOC. SDFN.

12-10-87 TIH, Tag bottom plug @ 6100'. Pull up to 5455'. Spot 10 sx. plug. Pull up to 4120', spotted 10 sx. plug. TOOH. RU casing scraper, tripped in w/25 stds. SDFN.

12-11-87 TIH to 3341' w/csg. scraper. TOOH, LD tbg. RU wireline, shot 4 holes @ 3310'. TIH w/E-Z drill cmt. retainer, set @ 3208'. Squeezed w/30 sx. cmt & spot 5 sx on top of retainer. TOOH w/setting tool. LD all but 1685' of tbg. TIH to 1687', spot 40 sx. plug. Trip up to 665, spot 10 sx. plug. TOOH laying down all tbg. RU perforators, shot 4 holes @ 347'. Circ. cmt. Cut off wellhead. Set dry hole marker w/10 sx.

18. I hereby certify that the foregoing is true and correct

SIGNED

Regina D. Davis

TITLE

Drilling Clerk

DATE

12-22-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Jayme E. Edwards

*See Instructions on Reverse Side