Form 3160-5 (December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

SF-078387A

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Lies "APPLICATION FOR REPMIT..." for such proposals.

6. If Indian, Allottee or Tribe Name

Use "APPLICATION FOR PERMIT" for such proposals		o. If indian, Another of Tribe Name
SUBMIT I	N TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well OIL WELL SMELL OTH 2. Name of Operator Amoco Production Company	ER Melissa Velasco-Price	8. Well Name and No. Kernaghan B 1A 9. API Well No.
3. Address and Telephone No.		30-045-22423
P.O. Box 3092 Houston, TX 77253	33 (281) 366-2548	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Blanco Mesaverde
		11. County or Parish, State
	T31N R08W Unit E	San Juan New Mexico
	s) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
_	Altering Casing	Conversion to Injection
	Other Plug Fruitland & conv	
	(Note: Report results of multiple of Recompletion Report and Log for	completion on Well Completion or
Amoco Production Company reques Mesaverde single producer per the a	COT 20	
14. I hereby certify that the foregoing is transland correspond to the signed with the foregoing is transland correspond to the foregoing is transland correspond to the foregoing is transland correspond to the foregoing is transland to the foregoing is transland.	ct Title Permitting Assistant	Date10/03/00
(This space for Federal or State office use)		_
Approved by	Title	Date 10/6/00
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Kernaghan B #1A Procedure

Procedure:

- 1. Check anchors. MIRU.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. If necessary, kill with 2% KCL water.
- 4. Nipple down WH. NU BOPs
- 5. TOH and LD 1-1/4" short string production tubing set at 3313'.
- 6. TOH with 2-3/8" long string production tubing set at 5927'.
- 7. RU WL unit. RIH and set 7" retrievable bridge plug at 3350'. Dump sand on top of RBP.
- 8. Squeeze Fruitland perforations as per Schlumberger design.
- 9. TIH and drill cement to 3325'. Pressure test squeeze to 500 psi.
- 10. Drill out remaining cement and retrieve 7" RBP.
- 11. Cleanout fill to PBTD at 5999'.
- 12. RIH with 2-3/8" production tubing. Reland production tubing at 5940'
- 13. ND BOPs. NU WH. Return well to production as Mesaverde single producer.