Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on re-			Form approved. Rudget Bureau No. 42-R/424. 5. LEASE DESIGNATION AND SERIAL NO.			
	G	GEOLOGICAL SURVEY			SF 078439 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
S (Do not use	UNDRY NOT this form for propos	CES AND REPORTED TION FOR PERMIT—"	ORTS ON W	ELLS different reservoir.	6. IF INDIAN, ACCOUNTS ON THIS SA		
1.					7. UNIT AGREEMENT NAME		
OIL GA	S OTHER	SHUT I	IN				
2. NAME OF OPERATOR					S. FARM OR LEASE NAME		
Union Texas Petroleum, A Division of Allied Chemical 3. ADDRESS OF OPERATOR Corporation 1860 Lincoln St., Suite 1010, Denver, Colorado 80295 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface					Johnston Federal 9. WELL NO.		
					#11 10. FIELD AND POOL, OR WILDCAT Blanco Pictured Cli 11. SEC., T., R., M., OR BLK. AND		
SE SW S	ec.7-T31N-I	R9W (1190'FS	SL-905'FWL)	•	Sec. 7-T31N-R9W		
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)			San Juan N. Mexico		
		6619'GL					
16.	Check Ap	propriate Box To Ir	ndicate Nature o	Motice, Report, or C	Other Data		
NOTICE OF INTENTION TO:					UENT REPORT OF:		
TEST WATER S	HUT-OFF	PULL OR ALTER CASING		ATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREA		MULTIPLE COMPLETE	F	RACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACID		ABANDON*	s	HOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL CHANGE PLANS (Other)					s of multiple completion on Well		
(Other)	og & evalua	ate		Completion or Recomp	letion Report and Log form.)		
17. DESCRIBE PROPOSED wor nent to this w	SED OR COMPLETED OPE	RATIONS (Clearly state and	all pertinent details, surface locations and	and give pertinent dates measured and true vertic	, including estimated date of starting al depths for all markers and zones i	any perti-	
Propos	al:						

- Set wire line cast iron bridge plug at 2900±.
- Run Schlumberger T.D.T. and cement bond log for evaluation of behind pipe formations.

The CIBP will not be removed as the bottom of the hole is junked. NOTE: After evaluating the logs, the proper forms will be submitted for either approval to plug back and recomplete or to abandon.

