

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON THE
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

2. NAME OF OPERATOR
Supren Energy Corporation

3 ADDRESS OF OPERATOR
J. C. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: **990' / South line & 990' / East line.**
AT TOP PROD. INTERVAL: **Same as above**
AT TOTAL DEPTH: **Same as above.**

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: ☐

SUBSEQUENT REPORT OF:

- TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*

-

MULTIPLE COPY
CHANGE ZONES
ABANDON* Call Number Change from Quinn No. 9 to No. 6-A.
(other) _____
Please state all pertinent information.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

17. DESCRIBE PROPOSED WORK OR REVISIONS TO EXISTING WORK (including estimated date of starting any proposed work, if known) *
measured and true vertical depths for all markers and zones pertinent to this work.)

Change well number from Quinn No. 9 to Quinn No. 6-A to comply with State Requirements.

Refracture and Resin Dakota formations.

Dual complete in Blanco Mesaverde and Basin Dakota formations. Perforate Dakota formation from 7900 ft. to 8050 ft. Frac w/approx. 40,000 gals of slick water and 25,000# 20-40 sand. Set Production Packer at approximately 6500 ft. Test Packer and perforate Mesaverde zone from approximately 5,000 ft. to 6100 ft. Sand water frac with approximately 80,000 gals water and 80,000# 20-40 sand. Clear sand off of Packer and string production tubing into packer. Run parallel string into Mesaverde zone. Nipple down dual tubing head. Clean up Dakota and Mesaverde zones. Test for leakage.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct.

SIGNED Rudy D. DeMott TITLE _____

(This space for Federal or State Office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE _____

***See Instructions on Reverse Side**

Budget Bureau Worksheet

5. LEASE	87 078511
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME	Quina
9. WELL NO.	6A
10. FIELD OR WILDCAT NAME	Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	Sec. 20, T-31N, R-8E, N.M.P.M.
12. COUNTY OR PARISH	San Juan
13. STATE	New Mexico
14. API NO.	30-045-23071
15. ELEVATIONS (SHOW DF, KDB, AND WD)	6592 DF

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

