UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135 Expires: March 31, 1993

FORM APPROVED

	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WITH SELECTIVE	" "SE U/8510
SUNDRY NOTICES AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or deepen or reentry to a different response to the such proposals in the such proposals	3ryqi5: 22
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas	A CONTRACTOR OF THE PROPERTY O
Oil Gas Well Well Other	
2. Name of Operator	8. Well Name and No.
VASTAR RESOURCES, INC.	BLANCO #1-A
Address and Telephone No.	9. API Well No.
1816 E. MOJAVE, FARMINGTON, NM 87401 (505) 599-4335	30-045-23259
Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area
	BLANCO MESAVERDE
	11. County or Parish, State
NWSE 1735' FSL & 1525' FEL Sec. 5, T-31N, R-8W	
	SAN JUAN COUNTY, NM
NATURE OF NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMISSION	
Notice of Intent Abandonment	Change
Recompletion	Change of Plans New Construction
Subsequent Report Plugging Back	Non-Routine Fracturing
Casing Repair	
	Water Shut-Off Conversion to Injection
Final Abandonment Notice	Conversion to Injection
Final Abandonment Notice Casing Repair Altering Casing	Conversion to Injection Dispose Water
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Work to commence approx 10/98:	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONG DIV.
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Work to commence approx 10/98: 1. Pull prod tbg. 2. Set CIBP @ 5390 to TA Lower MV. Select perf Cliffhouse/Menefee 499(3). Frac w/Halliburton Delta frac. 4. Set BP @ 4700. 5. Select perf Lewis Shale 4202-4686 6. Fr ac w/HES Delta frac. 7. CO Lewis, pull BP, CO Cliffhouse/Menefee. 8. Run tbg size determined after flow test, return well to production.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally 0-5365. DECEIVE SEP 2 5 1998
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Work to commence approx 10/98: Pull prod tbg. Set CIBP @ 5390 to TA Lower MV. Select perf Cliffhouse/Menefee 499: Frac w/Halliburton Delta frac. Set BP @ 4700. Select perf Lewis Shale 4202-4686 Fr ac w/HES Delta frac. CO Lewis, pull BP, CO Cliffhouse/Menefee. Run tbg size determined after flow test, return well to production.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONG DIV.
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Work to commence approx 10/98: 1. Pull prod tbg. 2. Set CIBP @ 5390 to TA Lower MV. Select perf Cliffhouse/Menefee 4990: 3. Frac w/Halliburton Delta frac. 4. Set BP @ 4700. 5. Select perf Lewis Shale 4202-4686 6. Fr ac w/HES Delta frac. 7. CO Lewis, pull BP, CO Cliffhouse/Menefee. 8. Run tbg size determined after flow test, return well to production.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONG DIV.
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONG DIV.
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONG DIV.
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CON. DIV. DIST. 3
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONG DIV.
Gasing Repair Altering Casing Other PAYADD	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CONS DIVS DISTIS
Final Abandonment Notice Casing Repair Altering Casing Other PAYADD	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is directionally DECEVED SEP 2 5 1998 OUL CON. DIV. DIST. 3

*See Instruction on Reverse Side

