Form 3160-5 (June 1990)

Approved by

Conditions of approval, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREAU	J OF LAND MANAGEMENT	1
Do not use this form for propo	TICES AND REPORTS ON WELLS peals to drill or to deepen or reentry to a different re ATION FOR PERMIT - " for such proposals	\ SF-078336
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gae Well Other 2. Name of Operator		8. Well Name and No.
Amoco Production Company	Attention:	Florance 114
3. Address and Telephone No.	Patty Haefele	3004523479
P.O. Box 800, Denver,	co 80201 (303) 830-4988	
4. Location of Well (Footage, Sec., T., R., M., or		Basin Fruitland Coal Gas
1850' FSL 860' FE	L Sec. 11 T 30N R 9W	Unit L San Juan New Mexico
12. CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE O	OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION		YPE OF ACTION
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion Recompletion Report and Log form.)
	rertical depths for all markers and zones pertinent to this work.)* y requests permission to plug and abandon thi 96.	is well per the attached procedure.
		MAR 2 8 1985
14. I hereby certify that the foregoing is true and co	· · · · · · · · · · · · · · · · · · ·	L CONL DIV.
signed Patty Ha	efele Title	Staff Assistant Date 03-19-1996
This space for Federal or State office use)	U	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCO

* See Instructions on Reverse Side

ex cu. Spen

APPROVED

SJOET Well Work Procedure

Florance 114

Version:

#1

Date:

March 19, 1996

Budget: Repair Type:

DRA **PXA**

Objectives:

To PXA the entire well

Pertinent Information:

Location:

L11 30N 09W, 1850 FSL 860 FWL

County:

San Juan

State: Lease: **New Mexico** BLM SF-078336

Well Flac:

980340

Horizon:

API #:

3004523479

Engr: Phone: Wyett/Deherrera H--(303)-368-7795

W-(303)-830-5578

Economic Information:

APC WI:050

Estimated Cost:

\$15,000.00

Formation Tops: (Estimated formation tops)

Nacimento:

Fruitland:

Ojo Alamo: Kirtland Shale:

1665 1785

2580

Pictured Cliffs:

2850

Menefee:

Point Lookout:

Mancos Shale: Gallup:

Graneros: Dakota:

6429 7188 7236

4810

5060

6860

Lewis Shale: Cliff House:

4602

Morrison:

Bradenhead Test Information:

Test Date:

BH

8/12/94 Tubing: 560 **CSG**

INT

Casing:

CSG

850

BH: 0

Time 5 min

10 min

15 min

Comments:

Florance 114
Orig. Comp. 4/80
TD = 2548,
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. RIH with tbg and spot 50' cement plug on top of retainer. POOH. Run in hole with tbg and CIBP, set CIBP at 2640'. Test csg integrity to 500#. Spot 100' cement plug on top. (17 cuft cement) Pull up hole and spot 100' cement plug across the Ojo Alamo at 1665' (33 cuft cement) and 266 to surface. (69 cuft cement)
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

FLORANCE 114. 649
Location — 11L— 30N— 9W
SINGLE frt
Orig.Completion — 4/80
Last File Update — 1/89 by JSI

