

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
2. NAME OF OPERATOR
Amoco Production Company
3. ADDRESS OF OPERATOR
501 Airport Drive Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 790' FNL x 1130' FWL, Section 16.
AT TOP PROD. INTERVAL: Same T31N, R6W
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other)

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐5. LEASE
SF-078766

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Rosa Unit

8. FARM OR LEASE NAME

9. WELL NO.

69

10. FIELD OR WILDCAT NAME

Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY CR
AREA

NW/4, NW/4, Section 16, T31N, R6W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

14. API NO.

30-045-23518

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6371' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well is an extremely low producer of natural gas. Amoco Production Company proposes to plug and abandon the well as follows:

1. Spot class "B" Neat cement plugs as follows:

1. Last 9' = mud between plugs

- a. 7850'-8075' (PBTD)-Dakota Plug - *dryline some cement into perfor*
- b. 7100'-7200'-Gallup Plug
- c. *5000-5100* 5350'-5450'-Mesaverde Plug *5700-5800 T*
- d. 3240'-3340'-Picture Cliffs Plug
- e. 2400'-2550'-Ojo Alamo Plug
- f. 1000'-1100'-Surface Sands *2800-3800 cas above*
- g. 0'-50'-Surface Plug *(over)*

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Adm. Supvr. DATE

3-13-80

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE


CONDITIONS OF APPROVAL, IF ANY:

APPROVED

APR 2 1980

CARL A. BARRICK
LEADING DISTRICT ENGINEER

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-149

2. Cut off wellhead, erect a plug and abandon maker.

3. Clean up location.

43109114