State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

2. Name of Operator Manana Gas, Inc. 3. Address & Phone No. of Operator 1002 Tramway Lane NE Address & Phone No. of Operator 1002 Tramway Lane NE	Sundry Notices and Reports on Wells				
Signature Signature Coll Coll			API	# (assigned by OCD)	
2. Name of Operator Manana Gas, Inc. 3. Address & Phone No. of Operator 1002 Tramway Lane NE Albuquerque, NM 87122 4. Location of Well, Footage, Sec., T, R, M Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790' FSL 1370' FEL Type of Submission Notice of Intent Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X. Other - Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Hartman Fresident JAN - 9 2002	1. Type of Well		5.		
Manana Gas, Inc. 3. Address & Phone No. of Operator 1002 Tramway Lane NE Albuquerque, NM 87122 4. Location of Well, Footage, Sec., T, R, M Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790' FSL 1370' FEL Type of Submission Notice of Intent Abandonment Recompletion Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8' CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Fel Hartman Mary Ackroyd Well No. #2 Pool Name or Wildca Aztec PC Extension 10. Elevation: New Construction New Construction Non-Routine Fracturing Vater Shut off Casing Repair Water Shut off Conversion to Injection X Other – Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8' CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE AN - 9 2002	OIL		6.	State Oil & Gas Lease	
8. Well No. #2 3. Address & Phone No. of Operator 1002 Tramway Lane NE Albuquerque, NM 87122 4. Location of Well, Footage, Sec., T, R, M Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790 FSL 1370' FEL Type of Submission Abandonment Change of Plans Recompletion Notice of Intent Recompletion Non-Routine Fracturing Water Shut off Altering Casing Repair Water Shut off Altering Casing Conversion to Injection X Other – Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: Jane Water Shut A JAN - 9 2002	2. Name of Operator	JAN 2002	7.	Lease Name/Unit Nan	
1002 Tramway Lane NE Albuquerque, NM 87122 4. Location of Well, Footage, Sec., T, R, M Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790' FSL 1370' FEL Type of Submission Notice of Intent Recompletion New Construction New Construction New Construction Noutine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection Tother - Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Head President President Date: JAN - 9 2002		OR COON ON	8.	Well No.	
Albuquerque, NM 87122 4. Location of Well, Footage, Sec., T, R, M Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790' FSL 1370' FEL Type of Submission Notice of Intent Recompletion New Construction New Construction New Construction Recompletion New Construction New Construction New Construction New Construction New Construction New Construction Recompletion New Construction New Const		ator 🤯		#4	
4. Location of Well, Footage, Sec., T, R, M Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790' FSL 1370' FEL Type of Submission Notice of Intent Notice of Intent Notice of Intent Notice of Intent New Construction Non-Routine Fracturing Casing Repair Non-Routine Fracturing Conversion to Injection X. Other - Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Fig. President President Date: JAN - 9 2002			9.	Pool Name or Wildcat	
Sec., 18 T-30-N, R-11-W, NMPM, San Juan County Unit J, 1790' FSL 1370' FEL Type of Submission Notice of Intent Notice of Intent Notice of Intent Recompletion New Construction New Constr	4 Leasting of Wall Footage Se	CTRM	10.		
Type of Submission Notice of Intent Notice of Intent Notice of Intent X Subsequent Report Final Abandonment Altering Casing Repair Altering Casing Conversion to Injection Water Shut off Altering Casing Conversion to Injection Other - Temp Abandon Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Ed Hartman This space for State Use)	Sec. 18 T-30-N. R-11-W. NMP	M. San Juan County			
Abandonment Change of Plans Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other – Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: I 1 0 V Ed Hartman This space for State Use)		,			
Abandonment Change of Plans Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other – Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: I 1 0 V Ed Hartman This space for State Use)	Type of Submission	Type of Action			
Recompletion New Construction Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Fresident Date: I I I I I I I I I I I I I I I I I I I		Abandonment Change of			
Casing Repair Water Shut off Altering Casing Conversion to Injection X_ Other - Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: JAN - 9 2002					
Altering Casing Conversion to Injection X Other - Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: Date:	X Subsequent Report			cturing	
X Other – Temp Abandon 13. Describe Proposed or Completed Operations Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: III I I I I I I I I I I I I I I I I I	T' IAI sadaanaah			iection	
Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE	Final Abandonment		11 10 111	10011011	
Manana attempted to Temporary Abandon this well by: 12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE	13 Describe Proposed or Comple	eted Operations			
12-18-01: Pull and LD 1910' of 1-1/4" IJ tubing. 12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: IT Date	13. Describe Froposed of Compre				
12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Fed Hartman President Date: 170	Manana attempted to Ter	nporary Abandon this well by:			
12-31-01: Set a 2-7/8" CIBP at 1848', 50' above perforations. 1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE Fed Hartman President Date: 170		21 - 5.4. 4.(4" 1.14) bin c			
1-3-02: Attempt to pressure test casing to 500#, leaked. Pressure up to 1000#, casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE President Date: 1/2/0 V Ed Hartman This space for State Use) JAN - 9 2002	12-18-01: Pull and LD 1910	D of 1-1/4 to tubing. Plat 1848' 50' above perforations.			
Casing bleed down to 100# in one minute. Plan to P&A well. SIGNATURE For Heads President Date: 1/2/0 V Ed Hartman This space for State Use) JAN - 9 2002	1_3_02: Attempt to press	ure test casing to 500#, leaked. Pressure u	ıp to 10	000#,	
SIGNATURE For State Use) Signature Fresident Date:	casing bleed do	wn to 100# in one minute.	•		
SIGNATURE For State Use) Signature Fresident Date:	Plan to P&A well				
(This space for State Use) JAN = 9 2002	Tian to Fast won.				
(This space for State Use) JAN = 9 2002	SIGNATURE 3d Hack	President Date:	1-10	> ~	
(This space for State Use) Title Date DAN = 9 2002	Ed Hartman				
Approved by Title Date	(This space for State Use)	MONTY Car o gar torranerent sixt at	1.4	N - 9 2002	
	Approved by	Title Date	UA	1N J LUUL	