1-File 4-USGS (Farmington) Form Approved. Form 9-331 E Budget Bureau No. 42-R1424 Dec. 1973 , o i UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR SF:081231-B 6. IF INDIAN, ALLOTTEE OR TRIBE NAME **GEOLOGICAL SURVEY** ೯೯೯೨ 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS = 37 5 (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 8. FARM OR LEASE NAME Pan Am Federal 1. oil gas **₹**x well well other 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME Dugan Production Corp. Basin Dakota 3. ADDRESS OF OPERATOR 11. SEC., T., R., M., OR BLK. AND SURVEY OR Box 208, Farmington, NM 5 5 E G T 클럽었다 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 Sec 24 T30N RI4W 500' FNL - 800' FWL below.) 12. COUNTY OR PARISH 13. STATE AT SURFACE: San Juan . ਡNM≅√ AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 11 to 12 to 13 to 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 5878! -GR 5 SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL Report results of multiple completion or zone 19 mange on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\* perf & frac (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, measured and true vertical depths for all markers and zones pertinent to this work.)\* 10**-**26-79 10-27-79 Perf 3-1/8" SSBII from 6239-6249, 6258-6270 35-6351 (19 holes) Western Co. rigged up and broke down zone 4/1300#. Fraced

including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and

Western Co. rigged up and tested BOP to 4000 psi - OK, pulled tbg.

w/73,000 gal. fluid, 80,000# 20-40 sand, 20 \$\int \textit{DFOFF} 10-\textit{20 sand} Aug. press 3000 psi @ 39 B/M, Max pressure 3700 psi @ 408B/M, Min press 2500 psi @ 36 B/M. Shut down pressure 1250 psi == SI pressure after 15 min 800 psi. 8 ö

> Preceded frac w/ 15% HCL down hole w/2 bbl free and next 100 bbl w/4 RCN balls per bbl. Total 40 balls. Ballsaction raiseds pressure to 4000 psi then breakdown occurr真母黃顏東wing 超过速jonal pumping action until 2nd ball off occurred with 4000 ខ្មែរ 💒

> > Cobing In Socia

brocon takapa popula

Subsurface Safety Valve: Manu. and Type			=== Set (	@ <u>~</u>	2 3 2 5 Ft.	
18. I hereby certify that the foregoing is t			of attack of the color of the c	5 ¥ . 12 ≸o :	17 C	1
SIGNED Thomas A. Dugar	Petro. Eng.	DATE _	= - = <del></del>	15 13	WOV TO COOK	4
V.	(This space for Federal or State office use)			<u></u>	The cold 3	
APPROVED BY	TITLE	_ DATE .			DIS!	

NMOCC