

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-0607

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Atlantic C

9. WELL NO.

6A

10. FIELD AND POOL, OR WILDCAT

Blanco MV/Blanco PC Ext

11. SEC., T., R., M., OR BLK. AND
SUBV. OR AREA

Sec. 6, T30N, R10W
NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Meridian Oil Inc.

3. ADDRESS OF OPERATOR

P.O. Box 4289 Farmington, New Mexico 87499

4. LOCATION OF WELL: Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1105'N, 810'W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, BT, GR, etc.)

6034' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DES. RIDE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The following has been completed to BLM specifications as stated in letter dated 12-23-87.

1. The fill material on the east side of the well location was reworked to control erosion problems.
2. A diversion along the edge of pad to divert water from going down the slope.
3. All disturbed areas were reseeded 9-1-88.

ADDITIONAL FOR RECORD

RECEIVED

SEP 22 1988

OIL OPERATIONS

SEP 20 1988

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

BY *B. King*

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Regulatory Affairs

DATE

9-15-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

1001 - Return to Bureau for any person knowingly and willfully to make to any department or agency of the