

5 USGS, Fmn

2 Wexpro

1 File

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well. Plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Dugan Production Corp.
3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 870' F L - 1070' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- REQUEST FOR APPROVAL TO:
- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON* ☒
- (other) ☐

SUBSEQUENT REPORT OF:

RECEIVED
DEC 10 1981
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to plug and abandon well as follows:

1. Fill 2-7/8" OD, 6.4#, J-55, 8R, EUE casing from 500' to surface using 14 sx cement.
2. Install permanent dry hole monument.
3. Fill all pits.
4. Clean well location of all equipment, pipe, junk, and trash.
5. Accomplish surface restoration as specified by the surface management agency or land owner.
6. Cut or remove tie-downs.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan TITLE Geologist

DATE 12-9-81 Set @ DEC 31 1981 Dean Elliott DISTRICT ENGINEER

APPROVED BY _____ TITLE _____ DATE DEC 31 1981
CONDITIONS OF APPROVAL, IF ANY:

NMOCC