

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 S. Pacheco

Santa Fe, New Mexico 87505-6429

WELL API NO.	3004523978
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	E1195
7. Lease Name or Unit Agreement Name	WAYNE MOORE COM
8. Well No.	1A
9. Pool Name or Wildcat	BLANCO MESAVERDE (PRORATED GAS)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	FOUR STAR OIL AND GAS COMPANY
3. Address of Operator	3300 N. Butler Ave., Suite 100 Farmington NM 87401
4. Well Location	Unit Letter <u>P</u> : <u>790</u> Feet From The <u>SOUTH</u> Line and <u>790</u> Feet From The <u>EAST</u> Line Section <u>16</u> Township <u>T31N</u> Range <u>R09W</u> NMPM <u>SAN JUAN</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ ADD PERFS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

FOUR STAR OIL & GAS COMPANY HAS COMPLETED THE FOLLOWING ON THE SUBJECT WELL:

5/7/98 - MIRU ND WELLHEAD, NU BOP. RELEASED PACKER, TOOH W/ TUBING AND PACKER. RIH W/ RBP, SET AT 4788'. RAN CBL/CCL LOG FROM 3150' - 4788'. RAN DIPOLE SHEAR ANISTROPY LOG FROM 3300' - 4788'. DROPPED SAND ON TOP OF RBP. PERFORATE LEWIS INTERVAL W/ 1 JSPF, 4" HEGS AT 4266', 4278', 4287', 4298', 4301', 4312', 4316', 4320', 4405', 4426', 4441', 4448', 4456', 4467', 4476', 4604', 4671', 4674', 4677', 4698', 4702', 4706', 4714', 4722', 4737', 4746', 4750', 4755', 4769'. SET PACKER AT 4783'. TEST RBP TO 4000 PSI, OK. PULL PACKER UP HOLE FOR FRAC. SPOT 200 GAL. 15% HCL ACROSS PERFS FROM 4266' - 4769'. BREAK DOWN WITH 1000 GAL 15% HCL. SET PACKER AT 4155'. FOAM FRAC INTERVAL W/ 657 BBL. 4% KCL, 920,000 CF NITROGEN, 205,383# 20/40 SAND.

5/15/98 - BAIL SAND OUT TO TOP OF RBP. PULL RBP. RUN PRODUCTION 2-3/8" TUBING TO 5392'. ND BOP, NU WELLHEAD. RETURN WELL TO PRODUCTION.

RECEIVED
JUN 1 1998
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allen Davis TITLE Operating Unit Manager DATE 6/12/98
TYPE OR PRINT NAME Allen Davis Telephone No. 325-4397

(This space for State Use)

APPROVED BY DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE JUN 24 1998

CONDITIONS OF APPROVAL, IF ANY: