UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

			Sun	dry Not	ices ar	ıd Repo	rts on V	Wells				· · · · · ·	
1. Ту	/pe of W GAS	/ell								5. 6.	SF If	ase Numb -078198 Indian, ibe Name	All. or
2 N -	me of O		<u> </u>					1		7.	Un	it Agree	ment Nam
		-	tor IGTO	7									
Ī	RESC	STI	RCES	1	& GAS	COMPANY	?		er lei Sa				
3. A d	dress £	Pho	ne No. o	f Onora	+			 -	er e	8.		ll Name	
			Farming			(505)	326-970	00		9.	AP	nray C #	ο.
1. Lc	cation 20'FNL,	of W	ell, Foo 'FWL, Se	tage, So	ec., T,	R, M	NMPM	-		10	. Fi	-045-240 eld and anco Mes	Pool
	·		,	,	., .	. 12 ///	1411111			11	. Co	unty and n Juan C	State
2. C	HECK AP	PROPI	RIATE BO	X TO IN	DICATE	NATITE	OF NOT	T C'E	REPORT,	Omrrai			
ТY	pe of S	ubmi	ssion				Type of	Acti	on	OTHE	K DA	ľA	
	N	otice	e of Int	ent		bandon	ment etion		Change New Con			_	
	X S	ubse	quent Re	port	F	luggin	g Back		Non-Rou				
	F	inal	Abandon	mont			Repair		Water S	hut d	off	,	
	•	IIIai	Abandon	ment	${X}$	ther -	g Casing Tubing	g repa	Convers	ion 1	to Ir	njection	
					~								
3.	Descri	be Pi	roposed	or Comp						<u> </u>			_
3.	Descrit 1-19-0 1-20-0 1-22-0	1 N 1 5	MIRU. TO	OH w/pur 4 jts 2 TIH w/p	np & ro 3/8" 4	perati ds. ND	ons WH. NU 55 tbg,	BOP.	TOOH w/	SN (a 515	og. SDON.	BOP.
4.	1-19-0 1-20-0 1-22-0	1 P 1 T	MIRU. TO FIH w/16 NU WH.	OH w/pur 4 jts 2 TIH w/p released	np & ro 3/8" 4 pump & d.	peration ds. ND .7# J-rods.	wH. NU 55 tbg, PT & pun	BOP. set mp ac	TOOH w/ @ 5189'. tion, OK	SN (9 515 ON.	56'. ND E	BOP.