

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
SUN OIL COMPANY

3. ADDRESS OF OPERATOR
2525 NW EXPRESSWAY OKLA. CITY, OK 73112

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1000' FNL & 120' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
NM 047

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N/A

7. UNIT AGREEMENT NAME
N/A

8. FARM OR LEASE NAME
New Mexico Federal -N-

9. WELL NO.
3E

10. FIELD OR WILDCAT NAME
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 18-T30N-R12W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5956' GR

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Drill		X

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8/09/80-Drld. to 3,684' w/Bit #3 7-7/8".

8/10/80-Drld. to 4,114' w/Bit #3 7-7/8".

8/11/80-Drld. to 4,331' w/Bit #3 7-7/8". While Making conn. @ 4331' and picking up Kelly w/pump on hole, got stuck w/Bit @ 4,305'. Unable to circ. or move pipe. Surged pump w/max of 1,800#. RU & Ran free point. Stuck @ 4,300'. Backed off @ 4,271'. TOOH. Now making up fishing tools.

8/12/80-Drld. to 4,434' w/Bit #4 7-7/8". GIHW/sub, JAR, bumper sub, accelerator. Screw into fish-Jarred same free. POOH. PU Bit #4. GIH-washed 30' to Btm.

8/13/80-Drld. to 4,803' w/Bit #4 7-7/8".

8/14/80-Drld. to 5,046' w/Bit #4 7-7/8".

8/15/80-Drld. to 5,359' w/Bit #4 7-7/8".

Subsurface Safety Valve: Manu. and Type _____ Set @ _____

18. I hereby certify that the foregoing is true and correct

SIGNED Janmie Owens TITLE Prod. Staff Assoc. DATE 8/18/80

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITION OF APPROVAL FOR RECORD

AUG 21 1980

BY BW
FARMINGTON DISTRICT

*See Instructions on Reverse Side

NMOCC



