

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS


(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE NM-03566	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Gage Com	
9. WELL NO. 1E	
10. FIELD OR WILDCAT NAME Basin Dakota	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T30N R10W	
12. COUNTY OR PARISH San Juan	13. STATE NM
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 6226' ground	

1. oil well <input type="checkbox"/>	gas well <input checked="" type="checkbox"/>	other <input type="checkbox"/>
2. NAME OF OPERATOR Tenneco Oil Company		
3. ADDRESS OF OPERATOR P. O. Box 3249, Englewood, CO 80155		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 810' FSL 790' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:		

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/> Correct information	



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The sundry notice of 2/26/82 mistakenly reported PBTD as 7300'. The corrected PBTD is 7287'.

The perforations reported on the completion report should read as follows:

7121-7130' KB 2 JSPF 9' - 18 holes
7203-7222' KB 1 JSPF 19' - 19 holes
28' - 37 holes

Subsurface Safety Valve: Manu. and Type _____

Set @ _____

18. I hereby certify that the foregoing is true and correct

SIGNED Don H. Morrison TITLE Production Analyst DATE 3/17/82
Don H. Morrison

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 24 1982

*See Instructions on Reverse Side

NMOCC

FARMINGTON DISTRICT
BY Snn