

All distances must be from the outer boundaries of the Section.


Operator <b>SUPRON ENERGY CORPORATION</b>			Lease <b>STATE COMM 31-8</b>		Well No. <b>1</b>
Unit Letter <b>M</b>	Section <b>2</b>	Township <b>31 NORTH</b>	Range <b>8 WEST</b>	County <b>SAN JUAN</b>	
Actual Footage Location of Well: <b>905</b> feet from the <b>SOUTH</b> line and <b>790</b> feet from the <b>WEST</b> line					
Ground Level Elev. <b>6604</b>	Producing Formation <b>Dakota</b> <b>Mesaverde</b>		Pool <b>Basin</b> <b>Blanco</b>	Dedicated Acreage: <b>5 1/2 307.12</b> Acres	

1. Outline the acreage dedicated to the subject well by colored pencil or hatchure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☒ Yes ☐ No If answer is "yes," type of consolidation Communitized

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.)

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division



CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

*Rudy D. Motto*  
Name

Rudy D. Motto

Position

Area Superintendent

Company

SUPRON ENERGY CORPORATION

Date

May 14, 1981

I hereby certify that the well location shown on this plat was plotted from field notes of surveys made by me or under my supervision and that the same is true and correct to the best of my knowledge and belief.

*Michael Daly*

Date Surveyed

March 31, 1981

Registered Professional Engineer  
and/or Land Surveyor

Michael Daly

Certificate No.  
5992