STATE OF NEW MEXICO						/
NERGY AND MINERALS DEPARTMENT	011 60	SNOTENA	TION DIVICION			<i>'</i> .
we, or torics accelves	OIL CO		TION DIVISION			Form C-103
DISTRIBUTION	C 2 21 T	P. O. BO	A Comment of the Comm	*		Revised 10-1-
SANTA FE	SANI	A FE, NEW	MEXICO 8750			<u>/</u>
U.S.G.S.				;	5a. Indicate Type	
LAND OFFICE				્લ જે	State	Fee X
OPERATOR			Agree, S.	1.40°	5. State Oil & Ga	s Lease No.
			4111		www	mmm
SUNDRY I GO NOT USE THIS FORM FOR PHOPOS USE **APPLICATION	NOTICES AND F	REPORTS ON PLUG B	ACE TO A DIFFERENT RESERVOIR.		7. Unit Agreemen	
OIL GAS WELL	OTHER-			The second section of the section of the second section of the section of the second section of the secti		
ame of Operator					8. Farm or Lease	Name
C. & E. Operators,	Inc.				Fee 9. Well No.	
Suite 1100, Two En	nergy Square	, Dallas,	Texas 75206		12 - A	
ocation of Well					10. Field and Poo	1 / /.01
UNIT LETTER A . 1010	FEET FROM T	HE North	LINE ANDF	EET FROM	Blanco	THE POTENT
THE East CINE, SECTION_	12	30%	12W	i		
THE CINE, SECTION _	TOW.	NSHIP	RANGE	NMPM.		
	15. Elevatio	n (Show whether	DF, RT, GR, etc.)		12. County	MANNY.
	5850	Gr.; 5362	KB		San Juan	
Check App	propriate Box T	o Indicate N	ature of Notice, Repor	t or Oth	er Data	
NOTICE OF INTE	•				REPORT OF:	
						_
FORM REMEDIAL WORK	PLUG A	ND ABANDON	REMEDIAL WORK			ING CASING
PURABLY ABANDON			COMMENCE DRILLING OPNS.	H	PLUG A	ND ABANDONMENT
L OH ALTER CASING	CHANGE	PLANS	CASING TEST AND CEMENT JOB Run produ	ction	casing	צן
			OTHER			
OTHER						
Describe I roposed or Completed Opera			ills, and give pertinent dates,	including	estimated date of s	starting any propose
work) SEE ROLE 1103. TD @	1:15 AM 6/2	4/82	Day Coombont IEC on	a cp/n	N loca Pa	n 7" casing
Drilled 8-3/4" hol	e with mud t	0 4992 · I	Ran Gearhart IES an	10 GK/D 2527	N 10gs. Na 81 . Rhr C	n / Casing
as follows: GS 1.	10'; 1 jt. 4	2.65; BKr	. FC 1.95'; 64 jts. 23 jts. 4996.53' of	- 73# K	οι, bkr. b	A TASC
1./3' & 58 jts. 24	21.29'. 10t	ar carry i	nt by HOWCO. Prece	de wit	h 1000 gal.	Flo-Check
SS casing. Stage	COLLAL AL 24	Pozmiv 6	#/sx. gilsonite &	2% CaC	1. Was dis	placing
and follow with 50	o sx. 30/30	t plug to	approx. 2800'. Shu	et down	. Opened s	tage
cement when pressu	re rose. Go	416' Dro	pped plug and close	d stag	e collar.	Set casing
collar and circula	iteu noie e 2	1e 6/25/8	2. Estimated top of	cemer	t @ 4200'.	Moved in
Silps and moved of	drilled out	ctage coll	ar at 2416' and tag	cemer	t @ 2741'.	Cleaned
prake Rig #25 and	dilited out	Tat Rond	log. Top of cement	6 4 19	O'. Perf.	3-0.4"
out cement to 4900	. Kan blue	ing and ci	rculated hole. Rar	a & set	HOWCO reta	iner @
notes at 3970 . P	ump down cas	the and cr	HOWCO-Lite, 64#/s>	. oils	onite & 2%	CaCl.
3930 and recement	. by howco wi	#/ov floc	ele. Circulated ce	ment t	o surface w	ith 14.5
followed with 100	SX. UI. D, 4	#/SX. IIOC лм 6/28/82	. WOC 24 hrs. Dri	illed o	out retainer	and
opent to 3070'	Clear out to	ASOO! R	an Gearhart CB log.	. Ceme	ent job OK.	Moved
off Drake Rig #25.	. Will move	in Drake R	ig #23 to complete	we11.	3	
5 <i>D</i> 1 6			· •			
hereby certify that the information abo	ove is true and comp	lete to the best of	of my knowledge and belief.			<u>in</u>
10 Lohn ME	Feller	* 11TLE	Consulatant		DATE July	5, 1982
John M. Heller T	CHAVEZ	· ·	SUPERVISOR DISTRICT # 3		.1111	7 1982