5 BLM, Fmn 1 File UNITED STATES

	Form Approved	1.
;	Budget Bureau	No. 42-R1424

m 9–331	5 BLM,	Fmn 1	File		2 Bunger co		
ec. 1973	HINITE	ED STATES		5. LEASE NM 0305	55-A [‡]	·	
	DEDARTMENT	OF THE INTER	RIOR			IBE NAME	
	DEPARTMENT	ICAL SURVEY		6. IF INDIAN, ALL	OTTEEOR		
				7. UNIT AGREEM	ENT NAME		
	Y NOTICES A	ND REPORTS	SON WELLS	7. UNII AGREEM			
SUNDR'	Y NOTICES A	drill or to deepen or	Solue bagloty a different	8. FARM OR LEA	SE NAME		
o not use this	Y NOTICES A form for proposals to orm 9–331–C for such	proposa(s.)	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Mexico	Federal	L	
				9. WELL NO.			
1. oil D	well XX 6	other DIS	1.3	- 1R			
	F OPERATOR		_	10. FIELD OR WIL	DCAT NAME		
DU	GAN PRODUCTI	ON CORP.		-I Rasin	Dakota	f. <u></u> -	
			м я7499	11. SEC., T., R.,	M., OR BLK. A	ND SURVEY OR	
		armington, N	TARLY See Space 17	4	4 =		
4. LOCATIO	N OF WELL (REPO	ORT LOCATION CL	EARLY, OCC OF	Sec.	10 T30N R	STATE .	
below.)	10501	FSL - 1650'	FWL	12. COUNTY OR	PARISH 13.	NM	
AT SUR	PROD. INTERVAL			San Ju	<u> </u>	•	
	AL DEDTH.			14. API NO.	27 7	:	
TO OUECK	APPROPRIATE BO	X TO INDICATE	NATURE OF NOTICE	15. ELEVATIONS	S (SHOW DF.	KDB, AND WD)	•
16. CHECK	, OR OTHER DAT	ΓΑ		5708'	GL; 5720	' RKB	
			UENT REPORT OF:	3700			•
REQUEST F	OR APPROVAL TO); 2002EQ					
TEST WATE	R SHUT-OFF L	1	RE	C = 1	<u></u> ;	-	
FRACTURE SHOOT OR	TREAT L	i		CHOTE: Poport	sults of multipl	e completion or zon	e
REPAIR WE	11	<u>j</u>	님		on Form 9-330.)		, i
PULL OR A	ALTER CASING]	님 ''	4N 23 1984 change	1731		
MUI TIPLE	COMPLETE []	H BUREAU OF	LAND MANAGENE			
CHANGE Z	ONES	亅		THE THE ARE	A	-	
ABANDON'	• l	}	\overline{v} 4½" casi	ng and cement	·	<u> </u>	- · . -
(other)				state all pertinent de	etails, and give	e pertinent date	s, ad
17 DESC	RIBE PROPOSED C	OR COMPLETED O	rongsed work. If well	state all pertinent de is directionally drillectionally drillectinent to this work.)*	d, give subsur	Tace locations of	
includ	ing estimated date	eal depths for all m	roposed work. If well narkers and zones per	tinent to this work.)		- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
measi	ured and true vertice	24. – - J			- 455	4	
					3 2 4 9		
				d comont			
c	coo attached	for details	of 4½" casing	and Cement.			
-	see accaches				- 돌창 내회	그림 필요시축	
					- 줄레틴션힞	三 著 多氮基本	
						그 젊 원칙으로	
					5 3 2 2		
					<u></u>		
					·	· · · · · · · · · · · · · · · · · · ·	
					- 		F4
		,			Set (<u> </u>	<u>.</u> Fl.
Subsurfa	ace Safety Valve: M	anu. and Type					
	reby certify that the	foregoing is true	and correct			n=h==n+=nn	์ กระกาย
18. I he	reby certify that the	and the	TITLE Geologi	St DATE _	_1-20-8 4 0	WEPTED FUN	- 代だ いけれ
SIGNED _	Jim Jim	L. Jacobs	-			O B the	4,3,3,0
		(m	his space for Federal or S		· 사람 : 중요	JAN 3 6	1984
	/		TITLE	DATE	:		لان جان
APPROVE	D BYONS OF APPROVAL,	IF ANY:				ican viùigenanth VM>	JURUE AIN
CONDITI	0,13 0				. nv	Sular	

DUGAN PRODUCTION CORP. Mexico Federal L #1R

Finished logging with Welex. T.I.H. Circulated bottoms up.
Laid down drill pipe. Rigged up and ran 143 jts. 4½" 0.D., 10.5#,
K-55, 8 Rd, ST&C casing. T.E 6513.11' set at 6507' RKB.

Cemented 1st stage w/ 10 bbls. mud flush followed by 250 sx class
"B" plus 8% gel and ¼# flocele per sk followed by 125 sx class
"B" with ¼# flocele per sk (Total cement slurry first stage =
625 cf). Reciprocated casing 0K while cementing. Good circulation
throughout job. Bumped plug with 1200 psi. Float held 0K. Job
complete at 9:50 p.m. 1-19-84. Dropped opening bomb. Opened
stage tool at 4521'. Circulated with rig pump for 3 hrs. Cemented
2nd stage with 10 bbls. mud flush followed by 550 sx 65-35 plus

4% gel and ¼# flocele per sk (total cement slurry 2nd stage = 1596 cf). Good circulation throughout job. Circulated all mud flush plus trace of contaminated cement. Closed stage tool with 2500 psi. Held OK. Job complete at 2:00 a.m. 1-20-84. Nippled down BOP. Set 4½" casing slips. Cut off 4½" casing. Released rig at 4:00 a.m. 1-20-84.

12% gel and 1# flocele per sk followed by 100 sx class "B" plus

