

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Designation and Serial No. <b>NM-06105</b>
2. Name of Operator <b>Amoco Production Company</b>		6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. <b>P.O. Box 800 Denver, Colorado 80201 (303) 830-4982</b>		7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <b>1090' FNL, 1640' FEL Sec. 14, T30N, R11W UNIT</b>		8. Well Name and No. <b>Federal Gas Com L #1E</b>
		9. API Well No. <b>30-045-95035</b>
		10. Field and Pool, or Exploratory Area <b>Basin Dakota</b>
		11. County or Parish, State <b>San Juan N.M.</b>

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent <input checked="" type="checkbox"/> Subsequent Report <input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Abandonment <input type="checkbox"/> Recompletion <input type="checkbox"/> Plugging Back <input type="checkbox"/> Casing Repair <input checked="" type="checkbox"/> Altering Casing <input type="checkbox"/> Other <u>Current Status</u> <input type="checkbox"/> Change of Plans <input type="checkbox"/> New Construction <input type="checkbox"/> Non-Routine Fracturing <input type="checkbox"/> Water Shut-Off <input type="checkbox"/> Conversion to Injection <input type="checkbox"/> Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

A casing leak has been found. Once it is repaired, the Dakota will be reevaluated for plugging and abandonment or production. Repair procedures will follow.

If there are any questions, please contact Ed Hadlock @ (303) 830-4982.

RECEIVED  
MAR 18 1993  
OIL CON. DIV.  
DIST. 3

RECEIVED  
BLM  
93 MAR 10 AM 11:23  
070 FARMINGTON, NM

14. I hereby certify that the foregoing is true and correct

Signed

*Ed Hadlock*

Title

*Business Analyst*

Date

*3/5/93*

(This space for Federal or State office use)

ACCEPTED FOR RECORD

Approved by

Title

MAR 10 1993

Conditions of approval, if any: